

Microscopic Analysis Report

Customer Name: Reservoir Description: ROBERT WILSON P610 TRANSAXLE OIL
 Sample Date:
 02/21/17

 Lab Number:
 655004

Discussion of Results

Ferrogram Interpretation: There were moderate amounts of abrasive/dust/dirt particles present on the slide. Also, there were a few ferrous/nonferrous white metal rolling wear platelet particles, ferrous/nonferrous white metal cutting wear particles, and spherical metallic wear particles observed on the slide. There were a few black oxide particles, ferrous/nonferrous white metal rubbing wear particles, and copper alloy rubbing wear particles found on the slide. The presence of rolling wear platelet particles suggests possible surface fatigue and/or rolling contact failure due to metal-to-metal sliding and/or abrasive contamination. The presence of cutting wear particles suggests possible misalignment and/or abrasive contamination. The presence of spherical metallic wear particles suggests possible rolling bearing fatigue and/or welding or grinding processes (contamination). The presence of black oxide particles suggests possible overheating and/or lubricant starvation. The morphology of abrasive/dust/dirt particles suggests possible contamination of the sample and/or reservoir from an external source. **Microscopic Analysis**





Figure 1: Ferrous Rolling Wear Platelet Particles, Ferrous Cutting Wear Particles, and Ferrous Rubbing Wear Particles at the Head of the Slide (Magnification 500X).



Figure 2: Large Ferrous Cutting Wear Particle and Abrasive/Dust/Dirt Particles at the Middle of the Slide (Magnification 500X).



R&G Laboratories, Inc. Tampa, FL Laboratory Services Division (813)643-3513