

2006 Toyota Tundra 4.7L Eng SR5

Print Date: 12/10/2016

M.I.L. "ON" DTC P0335 AND/OR P1340: INTERMITTENT HOT SOAK NO-START

TECHNICAL SERVICE BULLETIN

Reference Number(s): EG052-06, Date of Issue: August 24, 2006

TOYOTA: 2005 - 2006 4Runner (2UZ-FE), Land Cruiser, Sequoia, & Tundra (2UZ-FE)

SECTION: ENGINE

Introduction

Some customers may experience a M.I.L. "ON" condition with DTCs P0335 and/or P1340 with intermittent hot soak no-start. The camshaft position sensor assembly has been improved to prevent this concern.

- P0335 (Crankshaft Position Sensor "A" Circuit)
- P1340 (Camshaft Position Sensor "A" [Bank 1 Sensor 1])

Applicable Vehicles

- 2005 2006 model year 4Runner and Tundra vehicles equipped with the 2UZ-FE engine.
- 2005 2006 model year Land Cruiser and Sequoia vehicles.

Parts Information

PARTS INFORMATION

PREVIOUS FART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
19300-50010	19300-50030	Camshaft Position Sensor Assembly	

Warranty Information

WARRANTY INFORMATION

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG5036	R & R Camshaft Position Sensor Assembly	1.0	19300-50010	8A	99


Applicable Warranty*:

This repair is covered under the T oyota Comprehensive W arranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

Components

Fig 1: Identifying Camshaft Position Sensor Components



Required SSTs

SST CHART

ITEN NO.	SPECIAI	_ SERVICE TOOLS (SSTs)	PART NUMBER	QTY	DRW ⁽²⁾
1	Toyota Diagnostic Tester Kit (1) NOTE: All components from this kit/set are required. 12 Megabyte Diagnostic Tester Program Card (P/N 01002593-005) with version 13.4a Software (or later) is required.		TOY220036	1	9
2	CAN Interface Module Kit (1) NOTE: • All components from this kit/set are required.		01002744	1	9

- (1) Essential SSTs.
 (2) Refers to drawer number in SST Storage System.
 - NOTE: Additional Diagnostic Tester Kits, CAN Interface Modules, Program Cards, or other SSTs may be ordered by calling SPX/OTC at 1-800-933-8335.

Repair Procedure

- 1. Using the Diagnostic Tester, check for Diagnostic Trouble Codes (DTCs).
- 2. If DTCs P0335 and/or P1340 are present and the customer reports dif ficulty starting the vehicle when it is hot, refer to the T echnical Information System (TIS), 2005 2006 model year Repair Manual for applicable model: Ignition (2UZ-FE): Camshaft Position Sensor: Removal.

HINT:

Not ALL cases will include difficulty starting after a hot soak. If P0335 and/or P1340 are present and can be duplicated after clearing the DTCs with the Diagnostic Tester but the hot soak no-start condition is NOT duplicated, use the auto probe and monitor the camshaft position sensor output and compare with the illustration in the Diagnostics section of the Repair Manual for DTC P1340. If the camshaft position sensor signal waveform does NOT match, replace the camshaft position sensor.

- 3. Replace the camshaft position sensor.
- 4. Using the Diagnostic Tester, clear the DTCs.
- 5. Test drive the vehicle for a minimum of 10 minutes. Then use the Diagnostic T ester to verify that NO pending DTCs set.

Please Drive Safe!!!