


OBD reader returns code P0B56, 'Hybrid Battery Voltage Sense 'F' Circuit Low. Code was cleared but returned upon cycling ignition power.



*Figure 2 - OBD Reader codes returned*

Subsequently, the HV battery pack service plug was removed and the sense voltage connector was accessed for further testing. Connector, module casing and surrounding shielding shows carbon deposits consistent with high heat, smoke, and/or fire. Several wires appear melted and are disconnected. The voltage sense plug is also corroded/melted and unable to be disconnected safely – will require removal and further disassembly of HV to assess comprehensively.



*Figure 3 - Voltage sensor connector showing carbon deposits from smoke and/or fire*

The HV Battery pack was removed from vehicle and assessed for further damage. No evidence of external causes were located.



Figure 4 - Heat/carbon damage to module and cover plates

Superficial corrosion was observed on busbars and sense connectors.




Figure 5 - HV battery rear cell interface w. busbars





*Figure 6 - HV battery front cell interface w. busbars*



*Figure 7 - Corrosion on HV battery connections – right rear of back with melted sense wires far right*

Battery voltage sensor and harness was removed for further analysis



Figure 8 - 6 of 18 wires in sense harness have melted



Battery voltage sensor board internally appears ok, including soldered pins to board. Connector itself has sustained damage.





Figure 9 - Battery voltage sensor module board and connector


Plug is burnt/melted and required significant effort to remove, noting 2 of 18 connected male pins have the female terminal melted onto them.



*Figure 10 - Melted/burned connector.*


Underside of voltage sensor board also shows no visible issue, including sense harness connector





*Figure 11 - Underside of battery voltage sensor board*

The sense harness was disassembled, confirming that out of 18 wires, 6 had been completely melted and disconnected and a further 2 were partially damaged.



*Figure 12 - battery voltage sensor harness*

HV battery pack health was also assessed, with all 34 cell modules returning a voltage of 7.81v +/- 0.03v.

## Conclusion:

It appears the interface between the battery voltage sensor module and wiring harness may have developed a high resistance join resulting in excessive heating, melting and smoke and/or fire.

There was no evidence of external influence exacerbating this, including no mechanical, liquid or rodent intrusion.

Items requiring replacement include the voltage sensor module and battery voltage sensor harness.