LABOR & PARTS J# 1 10TOZ01 DRIVEABILITY CONCERN HOURS: 1.70 TECH(S):1196 CUSTOMER STATES THAT THERE IS A CLICKING NOISE WHEN SLOWING DOWN AND APPLING THE BRAKES AFTER INSPECTION FOUND NOISE COMING FROM THE DRIVERS SIDE FRONT AXLE REMOVED AND REPLACED AXLE AND OMITTED NOISE OP CODE 434601	WARRANTY	
PARTSQTYFP-NUMBER		
The state of the s	INTERNAL	C
PARTSQTYFP-NUMBERDESCRIPTIONUNIT PRICE- JOB # 2 TOTAL PARTS JOB # 2 TOTAL LABOR & PARTS		
J# 3 00TOZFLOORMAT FLOOR MAT DISCLAIMER HOURS: 0.00 TECH(S):1196 PROPER FLOOR MAT INSTALLATION AND CARE; NEVER INSTALL THE DRIVER'S FLOOR MAT WITH THE BOTTOM-SIDE UP, DO NOT PLACE ANOTHER FLOOR MAT(S) ON TOP OF AN EXISTING MAT, VERIFY THE DRIVER'S FLOOR MAT IS SECURED.		
PARTSQTYFP-NUMBERDESCRIPTIONUNIT PRICE- JOB # 3 TOTAL PARTS	0.00	
JOB # 3 TOTAL LABOR & PARTS	0.00	