
VIN:	JT2BK18U720065004
DECODED:	2002 Toyota Prius (Base)
Model Year:	2002
Make	Toyota
Model	Prius
Trim Level	Base

P3006 CODE DEFINITION:

- Battery State of Charge Uneven

2 POSSIBLE CAUSES

- Battery pack has failed
- HV Battery ECU has failed

TOP REPORTED FIX:

- Replaced High Voltage (HV) Battery

FREQUENTLY REPORTED FIXES:

- Replaced Battery
- Repaired High Voltage (HV) Battery w/P3000
- Replaced High Voltage Traction Battery Wiring w/P3000

OTHER REPORTED FIXES:

- Replaced Alternator
- Replaced Battery Energy Control Module (BECM) w/P3000, P3001, P3027
- Removed Battery Service Plug
- Replaced Hybrid Battery Control Module w/C1213, C1259, P3000...

Disclaimer:

www.lemurmonitors.com/eula.html

The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.