

B CUSTOMER STATES CAT CONVERTER WAS STOLEN PLEASE INSPECT AND PROVIDE
ON ESTIMATE FOR REPAIRS

10 REPLACED CAT CONVERTER

4717 CTC 1.00			175.21	175.21
2 90901-05026 BOLT, WASHER BASED H	15.63		15.63	31.26
2 90501-A0006 SPRING, COMPRESSION	7.90		7.90	15.80
1 17410-21500 PIPE ASSY, EXHAUST,	2438.32		2438.32	2438.32
1 17451-23010 GASKET, EXHAUST PIPE	33.93		33.93	33.93
1 17451-21060 GASKET, EXHAUST PIPE	78.20		78.20	78.20
2 90501-A0031 SPRING, COMPRESSION	7.97		7.97	15.94
2 90080-10291 BOLT	7.43		7.43	14.86
10 REPLACED DOWNSTREAM O2 SENSOR				
4717 CTC 0.80			140.17	140.17
1 89465-47070 SENSOR, OXYGEN	186.84		186.84	186.84
10 DIAGNOS AND PERFORMED POSTSCAN				
4717 CTC 1.30			193.84	193.84
10 BUILT AND INSTALLED CAT CONVERTER SHIELD				
4717 CTC 2.00			350.42	350.42

PARTS: 2815.15 LABOR: 859.64 OTHER: 0.00 TOTAL LINE B: 3674.79

170181 UPON INSPECTION TECH FOUND CAT CONVERTER STOLEN. REPLACED
CAT CONVERTER, O2 SENSOR, AND RELATED BOLTS AND GASKETS. PERFORMED
POST-SCAN TO VERIFY PROPER OPERATION. NO FURTHER RELATED REPAIRS NEEDED
AT THIS TIME. CUSTOMER REQUESTED CAT SHIELD BE INSTALLED ON VEHICLE.
CUSTOMER SUPPLIED PARTS. BUILT AND INSTALLED CAT SHIELD.