

[Home](#) > [Toyota](#) > **T-SB-0041-15**



## Toyota TSB T-SB-0041-15

**Make:**

Toyota

**Number:**

T-SB-0041-15

**Title:**

MIL "ON" DTC P0A0F, P3190, P3191, P0171 Due to Purge VSV Vacuum Line Separation

**Date:**

6/30/2015

**Models:**

2012-2013 Prius v

**Summary:**

Some 2010 - 2013 model year Prius and 2012 - 2013 model year Prius V vehicles may exhibit a MIL "ON" condition with Diagnostic Trouble Code(s) (DTCs) P0A0F (Engine Failed to Start), caused by Purge VSV/PCV line separation from the throttle body housing. One or more of the following DTCs may also set: P3190 (Poor Engine Power); P3191 (Engine Does NOT Start); P0171 (System Too Lean [Bank One]). Replace the Purge VSV (Vacuum Switching Valve Assembly) and reprogram the Engine Control Module/ECM (SAE term: Powertrain Control Module/PCM) with the latest calibration to address this condition.



[Hide](#)

Enter your keywords here



**Search for**

- All of these words  This exact phrase  Any of these words

**Filter by**

Make	<input type="text" value="Select Make"/>
Model	<input type="text" value="Select Model"/>
Year	<input type="text" value="Select Year"/>
Number	<input type="text"/>
Date	<input type="text" value="mm/dd/yyyy"/>
DTC	<input type="text"/>