

USB/iPod Not Recognized

Service

Category Audio/Visual/Telematics

Section Audio/Video Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2010	Prius	

Introduction

Some 2010 Prius vehicles equipped with navigation may exhibit intermittent operation of USB/iPod[™] devices while in use. A newly designed Multi-Media Interface ECU is now available to correct this condition.

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
PT233-47100	861A1-0E020	Computer, Multi-Media Interface	1
PT233-47100-HW	Same	USB Hardware Kit	1

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
ZT6708	R & R Multi-Media Interface ECU	0.3	PT233-47100	81	74

APPLICABLE WARRANTY

- Toyota accessories installed as original equipment are covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Toyota accessories installed after the new vehicle purchase are warranted for 12 months, regardless of mileage, from the date of installation on the vehicle, or the remainder of the applicable New Vehicle Limited Warranty, whichever provides the greater coverage.
- Toyota accessories purchased over-the-counter are covered for 12 months from the date of purchase.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.



USB/iPod Not Recognized

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Plastic Pry Tool Set*	00002-06000-01	1

^{*} Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Repair Procedure

- 1. Confirm condition.
- 2. Replace the USB ECU.

Refer to the Technical Information System (TIS), *Accessory – Accessory Installation* – <u>"2010 Prius USB Interface Kit PT233-47100 Rev. A"</u>

3. Verify proper operation.

NOTE

Do not cut wire harness wire ties, unless necessary.