

A/C Control Display Difficult to Read

Service Category Vehicle Interior

Section Heating/Air Conditioning

Market USA

Toyota Supports
 ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2010	Prius	

Introduction

Some 2010 model year Prius vehicles may have an A/C control panel electronic display that is blurry, cloudy, or difficult to read. An improved A/C control panel has been made available to improve this condition.

Production Change Information

This TSB applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
Prius	Tsustsumi (Line 1)	JTDKN3DU#A0037997
	Tsustsumi (Line 2)	JTDKN3DU#A1057683
	Toyota Auto Body	JTDKN3DU#A5047048

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
AC9010	R & R A/C Control Assembly	0.4	55900-470#0	67	63

APPLICABLE WARRANTY

- This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

A/C Control Display Difficult to Read

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
55900-47020	Same	Control Assembly, Air Conditioner	1
55900-47030	Same		1

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST'S)	PART NUMBER	QTY
Plastic Pry Tool Set*	00002-06000-01	1

* Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Repair Procedure

1. Confirm the A/C control panel display is difficult to read.
2. Remove and replace the A/C control assembly.

Refer to the Technical Information System (TIS), 2010 model year Prius Repair Manual:

Vehicle Interior – Heating/Air Conditioning – “Heating / Air Conditioning: Air Conditioning Panel: [Removal](#) and [Installation](#)”

3. Verify proper operation.