

LABOR & PARTS

J# 1 12T0Z0ILCONSUMP OIL CONSUMPTION

UNITS: 1.00 TECH(S): 253

95.00

PERFORM OIL CONSUMPTION TEST
 INSPECTED VEHICLE FOR EXCESSIVE OIL USAGE. REMOVED SPARK PLUG
 TO VISUALLY INSPECT ALONG WITH PERFORMING A CYLINDER LEAK
 DOWN TEST. FOUND ALL CYLINDERS EQUALLY LOOSING PRESSURE BY
 PISTON RINGS. BORE SCOPE INSPECTION FOUND SCORING PRESENT
 SUGGESTED REPAIRS ARE TO REPLACE ENGINE SHORT BLOCK ALONG
 WITH SENDING CYLINDER HEAD FOR SUBLET REPAIRS. CUSTOMER WAS
 PROVIDED EST. ON COST INVOLVED.
 5,739.97

JOB # 1 TOTAL LABOR & PARTS

95.00

[] CASH [] CH

CK. NO. []

[] AMER X PRESS

[] VISA [] MASTE

ADDITIONAL
 AVAIL

• Alignments
 of your vehicle