

CUSTOMER #: 1012382

805619



DCH TOYOTA / SCION
TORRANCE



INVOICE

2955 PACIFIC COAST HIGHWAY
TORRANCE, CA 90505-6739
310-325-7602

STEVE CAREY
316 N FRANCISCA AVE
REDONDO BEACH, CA 90277
HOME:310-251-8805 CONT:310-251-8805
BUS: CELL:310-498-5289

PAGE 1

SERVICE ADVISOR: 114958 Jose A. Hernandez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	07	TOYOTA PRIUS	JTDKB20U977583090		111888/111888	268...	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
09SEP09 DD			18:00	22SEP17	129.50	CASH	22SEP17
R.O. OPENED	READY	OPTIONS: DLR:04078 ENG:1.5_Liter_DOHC_Hybrid					
08:22	22SEP17	16:17	22SEP17				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CLIENT STATES THAT THE CHECK ENGINE LIGHT IS ON CHECK AND ADVISE (WAS TOLD IT WAS A INVERTER PUMP)
 CAUSE: PERFORM INSPECTION FOUND DTC P1121 COOLANT FLOW CONTROL VALVE.
 AND ALSO RECOMMEND TO REPLACE THE THERMOSTAT

M CUSTOMER STATES

116261	CA					589.89	589.89
1	16670-21010	VALVE ASSY, WATER W/			196.78	196.78	196.78
1	00272-SLLC2	SUPER LONG LIFE COOL			23.05	23.05	23.05
1	16325-62010	GASKET, WATER INLET			16.06	16.06	16.06
1	90916-03093	THERMOSTAT			51.64	51.64	51.64
PARTS:	287.53	LABOR:	589.89	OTHER:	0.00	TOTAL LINE A:	877.42

INSTALL NEW COOLANT FLOW CONTROL VALVE, INSTALL NEW THERMOSTAT. NO ADDITIONAL RECOMMENDATIONS

B PERFORM DEALER SUGGESTED COOLING SYSTEM FLUID EXCHANGE \$149.95. THIS SERVICE IS DESIGNED TO REPLACE VIRTUALLY ALL OF THE OLD DEPLETED COOLANT AND REPLACE IT WITH NEW COOLANT AND SYSTEM TREATMENT.

CAUSE: EXCHANGE COOLANT FOR \$149.95
 CEXCH PERFORM DEALER SUGGESTED COOLING SYSTEM FLUID EXCHANGE \$149.95. THIS SERVICE IS DESIGNED TO REPLACE VIRTUALLY ALL OF THE OLD DEPLETED COOLANT AND REPLACE IT WITH NEW COOLANT AND SYSTEM TREATMENT.

116207	CA					108.42	108.42
HAZ HAZARDOUS WASTE REMOVAL						2.85	2.85
1	00272-SLLC2	SUPER LONG LIFE COOL			23.05	23.05	23.05
PARTS:	23.05	LABOR:	108.42	OTHER:	2.85	TOTAL LINE B:	134.32

C PERFORM DEALER SUGGESTED TRANSMISSION FLUID EXCHANGE. THIS SERVICE IS DESIGNED TO REMOVE VIRTUALLY ALL OF THE OLD DEPLETED TRANSMISSION FLUID FROM THE SYSTEM AND REPLACE IT WITH NEW FLUID AND SYSTEM FORTIFIER.

CAUSE: TRANSMISSION FLUID EXCHANGE DEX III

<p><i>Thank You!</i></p> <p>ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE.</p> <p>OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE REQUIRED TIME.</p>	<p>SERVICE DEPARTMENT HOURS: MONDAY THROUGH FRIDAY 7:00 AM TO 7:00 PM</p>	<p>ORIGINAL ESTIMATE</p>	<p>AUTHORIZED ADDITIONS</p>	<p>DESCRIPTION</p>	<p>TOTALS</p>
	<p>PARTS AND CASHIER HOURS: MONDAY THROUGH FRIDAY 7:00 AM TO 7:00 PM</p>	<p>NOTICE TO CONSUMER PLEASE READ IMPORTANT INFORMATION ON BACK</p> <p>I acknowledge notice and oral approval of an increase in the original estimated price and authorize any additional warranty service.</p>	<p>LABOR AMOUNT</p>	<p>PARTS AMOUNT</p>	<p>GAS, OIL, LUBE</p>
<p>SATURDAY HOURS: 7:30 AM TO 5:00 PM BY APPOINTMENT ONLY</p>	<p>X</p>	<p>MISC. CHARGES</p>	<p>TOTAL CHARGES</p>	<p>INSURANCE/DISCOUNTS</p>	<p>SALES TAX</p>
		<p>CUSTOMER SIGNATURE</p>		<p>PLEASE PAY THIS AMOUNT</p>	

CUSTOMER #: 1012382

805619



DCH TOYOTA / SCION TORRANCE



INVOICE

2955 PACIFIC COAST HIGHWAY TORRANCE, CA 90505-6739 310-325-7602

STEVE CAREY 316 N FRANCISCA AVE REDONDO BEACH, CA 90277 HOME:310-251-8805 CONT:310-251-8805 BUS: CELL:310-498-5289

PAGE 2

SERVICE ADVISOR: 114958 Jose A. Hernandez

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Includes vehicle details for a 2007 Toyota Prius.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists service items like 'TEXCH PERFORM DEALER SUGGESTED TRANSMISSION FLUID EXCHANGE' and 'HAZ HAZARDOUS WASTE REMOVAL'.

D ADVISE IF THE THERMOSTAT SHOULD BE REPLACE ON THIS SERVICE M CUSTOMER STATES 116207 CA 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

E INSPECT ALL LOWER ENGINE COVERS M CUSTOMER STATES 116207 CA 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

F ADJUST ALL TIRES TO FACTORY SPECS LF ___ PSI RF ___ PSI LR ___ PSI RR ___ PSI CAUSE: ADJUST ALL TIRES TO FACTORY SPECS LF ___ PSI RF ___ PSI LR ___ PSI RR ___ PSI CARB ADJUST ALL TIRES TO FACTORY SPECS LF ___ PSI RF ___ PSI LR ___ PSI RR ___ PSI 116207 CA 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE F: 0.00

G PERFORM DCH EXPERIENCE MULTI-POINT INSPECTION. TIRE PRESSURES HAVE BEEN RECORDED ON HARD COPY. YOUR NEXT SERVICE APPOINTMENT WILL BE ON PLEASE CONTACT US TO CHANGES.

Thank You!

SERVICE DEPARTMENT HOURS: MONDAY THROUGH FRIDAY 7:00 AM TO 7:00 PM PARTS AND CASHIER HOURS: MONDAY THROUGH FRIDAY 7:00 AM TO 7:00 PM SATURDAY HOURS: 7:30 AM TO 5:00 PM BY APPOINTMENT ONLY

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE REQUIRED TIME.

Table with columns: ORIGINAL ESTIMATE, AUTHORIZED ADDITIONS, DESCRIPTION, TOTALS. Includes a 'NOTICE TO CONSUMER' section and a signature line.

BAR # ARD 169056 EPA # CAL 000325865

WARNING: Motor vehicles contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. These chemicals are contained in many vehicle components and replacement parts, vehicle fluids, and paints and materials used to maintain vehicles, including, but not limited to, fuel, oil, batteries, brakes, and wheel balancing weights.

CUSTOMER #: 1012382

805619



**DCH TOYOTA / SCION
TORRANCE**



INVOICE

2955 PACIFIC COAST HIGHWAY
TORRANCE, CA 90505-6739
310-325-7602

STEVE CAREY
316 N FRANCISCA AVE
REDONDO BEACH, CA 90277
HOME:310-251-8805 CONT:310-251-8805
BUS: CELL:310-498-5289

PAGE 3

SERVICE ADVISOR: 114958 Jose A. Hernandez

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	07	TOYOTA PRIUS	JTDKB20U977583090		111888/111888	268...	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
09SEP09 DD			18:00	22SEP17	129.50	CASH	22SEP17
R.O. OPENED	READY	OPTIONS:					
08:22	22SEP17	16:17	22SEP17	DLR:04078 ENG:1.5_Liter_DOHC_Hybrid			

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
CAUSE: COURTESY MULTI POINT INSPECTION							
LMPI PERFORM DCH EXPERIENCE MULTI-POINT INSPECTION. TIRE PRESSURES HAVE BEEN RECORDED ON HARD COPY. YOUR NEXT SERVICE APPOINTMENT WILL BE ON _____ PLEASE CONTACT US TO CHANGES.							
116207 CA						0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE G:	0.00

EST: 454.89 22SEP17 08:22 SA: 114958

I authorize DCH Toyota/Scion of Torrance to contact me at my above noted telephone number on any matter concerning my vehicle.

X _____

Thank You!

SERVICE DEPARTMENT HOURS:
MONDAY THROUGH FRIDAY
7:00 AM TO 7:00 PM

PARTS AND CASHIER HOURS:
MONDAY THROUGH FRIDAY
7:00 AM TO 7:00 PM

ALL PARTS ARE NEW
UNLESS SPECIFIED
OTHERWISE.

SATURDAY HOURS:
7:30 AM TO 5:00 PM
BY APPOINTMENT ONLY

OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE REQUIRED TIME.

ORIGINAL ESTIMATE	AUTHORIZED ADDITIONS	DESCRIPTION	TOTALS
\$	\$	LABOR AMOUNT	896.75
		PARTS AMOUNT	362.51
NOTICE TO CONSUMER PLEASE READ IMPORTANT INFORMATION ON BACK			
I acknowledge notice and oral approval of an increase in the original estimated price and authorize any additional warranty service.			
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	5.70
		TOTAL CHARGES	1264.96
		INSURANCE/DISCOUNTS	0.00
		SALES TAX	33.53
		PLEASE PAY THIS AMOUNT	1298.49
X	CUSTOMER SIGNATURE		

BAR # ARD 169056 EPA # CAL 000325865

WARNING: Motor vehicles contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. These chemicals are contained in many vehicle components and replacement parts, vehicle fluids, and paints and materials used to maintain vehicles, including, but not limited to, fuel, oil, batteries, brakes, and wheel balancing weights. In addition, motor vehicles emit engine exhaust and fumes, and when serviced, cleaned, or maintained generate used oil, waste fluids, fumes, grease, grime, and particulates from component wear, which contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. (Posted in accordance with Proposition 65 in Cal. Health & Safety Code §25249.5 et seq.) For further information about Proposition 65: <http://www.oehha.org/prop65.html>