Qty (or Hours)	,	Description	Total
0.5 (Hrs)	Diagnosis	Test, inspect, and research in order to determine cause of root complaint.	\$45.00

(Labor Rate = \$90/Hr)

Notes:

Customer requests a checkover for a recently purchased vehicle. We note typical corrosion for a vehicle of this age in this area, a mild oil leak from right rear corner of engine, likely from either the head gasket or oil pressure sender, ~20% brake pads (est. \$325) remaining in front, ~70% in rear, floppy rear wiper blade (est. \$17) and oil drain under-cover attached with zip ties.

The parts and accessories sold and installed, and service connected with the installation and adjustments of the parts and accessories sold and installed are guaranteed to be free from defects in material and workmanship under normal service and use until such parts and accessories have been driven, used, or operated for a distance of 20,000 miles or a period of two years, from date of service, whichever first occurs, unless otherwise stated under the part or

service listed above. All parts are new unless otherwise stated.

My signature below acknowledges as true my authorization of the above parts and labor, either in person or by phone. In addition I acknowledge as true the above logged authorization and the above charges as equitable and in line with my expectations.

Parts		
\$0.00	Subtotal:	\$45.00
Labor	Sales Tax:	\$3.94
\$45.00	Adustments(-)	\$0.00
	Workorder Total	\$48.94

TaxExempt Total:

Amount Due: \$48.94