

Service Record Details for Your 2010 Prius

DATE	12/27/2016	VEHICLE	2010 Prius
TYPE	Dealer	VIN	JTDKN3DU6A0241409
REPAIR ORDER #	0160007	MILEAGE	175959
PROVIDER	Toyota of Fort Walton Beach 777 Beal Parkway N Ft Walton Beach, FL 32547	CUSTOMER	DONALD MONTGOMERY
SERVICES		NOTES	

JOB	DATE	OPERATION	DETAILS	PAYMENT
1	12/27/2016	PERFORM MULTI POINT MAINTENANCE	PERFORM MULTI POINT MAINTENANCE INSPECTION AND REPORT CONDITION ~ ~ ~ ~	CUSTOMER PAY
2	12/27/2016	REPLACE INVERTER ASSEMBLY W/ CON	(C) CUSTOMER STATES HYBRID SYSTEM ERROR MESSAGE IS DISPLAYED, CHECK AND ADVISE ~ ~14-05 ~ ~175958 PERFORMED HEALTH CHECK P0A94, INFOCODE 532, P324E INFO CODE 172 CURRENT INHYBRID SYSTEM. REMOVED INVERTER TO INSTALL LIPM. FOUND INVERTER TO BE ARCHED INSIDE FOROMVOLTAGE SPIKE. CREATED TECH CASE #TA163570141SPOKE WITH JAY. INFORMED TO INSTALL NEW INVERTER UNDER WARRANTY ENHANCEMENT. CLEARED ALL FAULTS.	WARRANTY PAY