

PRODEMAND

YMMS: 2001 Toyota Prius

Engine: 1.5L Eng

VIN:

Nov 25, 2019

License:

Odometer:

Fig 1: DTC P3115 Chart

| DTC No. | DTC Detecting Condition | Trouble Area |
|---------|--|--|
| P3115 | Failure or open circuit in battery current sensor. (2 trip detection logic) | <ul style="list-style-type: none"> • System main relay (Battery current sensor) • Wire harness |

G02805805

Courtesy of © TOYOTA, LICENSE AGREEMENT TMS1002

Reprinted Under License from Toyota Motor Sales, U.S.A., Inc., License Agreement TMS1002