

2012 Toyota Prius
JTDMN3DU2C1581265
Engine: 1.8L L4 (2ZR-FXE)
FULL HYBRID EV-GAS
(FHEV) FI

GRAND TOTAL: \$190.53

✓ PAID

SERVICES

1 OVERHEATING

SUBTOTAL: \$175.00

LABOR

Labor: \$175.00
Parts: \$0.00
Fees: \$0.00
Sublet: \$0.00

CUSTOMER STATES VEHICLE OVERHEATS AT TIMES WHILE DRIVING ON THE HIGHWAY. CHECK FOR CODES, SEE ATTACHED REPORT. FOUND CODE:
P0117 Engine coolant temperature circuit input low permanent
P3190 Poor engine power permanent
P3191 Engine not start permanent
PERFORM ANALYSIS. NOTED EXCESSIVE AIR IN ENGINE COOLING SYSTEM. PUT VEHICLE INTO MAINTENANCE MODE AND BLEED COOLING SYSTEM. NOTED VEHICLE IS BURNING ANTIFREEZE (SEE ATTACHED VIDEO), LIKELY HEAD GASKET PROBLEM. ALSO NOTED VEHICLE HAS ANTIFREEZE LEAK NEAR RADIATOR, TEARDOWN REQUIRED TO FIND SOURCE OF LEAK BUT LIKELY RADIATOR LEAKING. SEE ATTACHED VIDEO. CUSTOMER ADVISED.

FINDINGS

VEHICLE HAS SIGNS OF ANTIFREEZE LEAK FROM RADIATOR AREA.



[https://services.shop-](https://services.shop-ware.com/uploads/v1/original/SaG5DUAlIwcTNLErcOmnv)

[ware.com/uploads/v1/original/SaG5
DUAlIwcTNLErcOmnv](https://services.shop-ware.com/uploads/v1/original/SaG5DUAlIwcTNLErcOmnv)

VEHICLE BURNING ANTIFREEZE



[https://services.shop-](https://services.shop-ware.com/uploads/v1/original/S_2dapbF5ohswA_h0suCR)

[ware.com/uploads/v1/original/S_2d
apbF5ohswA_h0suCR](https://services.shop-ware.com/uploads/v1/original/S_2dapbF5ohswA_h0suCR)

FAULT CODE REPORT ATTACHED



[https://services.shop-](https://services.shop-ware.com/uploads/v1/original/x_PmzzHqci-nj95EvQKZP)

[ware.com/uploads/v1/original/x_Pm
zzHqci-nj95EvQKZP](https://services.shop-ware.com/uploads/v1/original/x_PmzzHqci-nj95EvQKZP)