



Original Customer Requests

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ A. PERFORM TOYOTA CARE/SCION BOOST COMPLIMENTARY 5K SERVICE PERFORM 6 MONTH OWNER SERVICE WHICH INCLUDES COMPLETE MUTLI POINT INSPECTION, TIRE ROTATION, TOP OFF FLUIDS, INSPECT OIL LEVEL.
- ✓ B. COMPLIMENTARY MULTI-POINT INSPECTION.
- ✓ C. TIRE PRESSURE CHECK AND INFLATION SERVICE



Package Results

Penske Toyota Scion of West Covina World Class Inspection (1)

Passed Task	Observation	Recommendation	Done
Fill windshield washer fluid	Found washer fluid level low: Filled to proper level		
Measure rear brake pads/shoes	6 mm or greater: Inspect brakes next service		
Measure front brake pads	6 mm or greater: Inspect brakes next service		
Left front tire tread depth	Left front tire tread measures 6/32" or greater: Inspect tire next service		
Left rear tire tread depth	Left rear tire tread measures 6/32" or greater: Inspect tire next service		
Right front tire tread depth	Right front tire tread measures 6/32" or greater: Inspect tire next service		
Right rear tire tread depth	Right rear tire tread measures 6/32" or greater: Inspect tire next service		
Check and adjust front tire pressures	Tire pressure was set to 36 psi - Check tire pressures monthly		
Inspect overall tire wear and condition	All tires require inspection next service		
Check and adjust rear tire pressures	Tire pressure was set to 37 psi - Check tire pressures monthly		