



## MX-Sensor\_V6.10 Function List For US Market (Note:For reference only)

**NOTES:**

● This function is supported. ○ This function is not supported. Mark explaining (Red:New, Yellow: Modify)

**Special Declaration:**

- 1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Abarth	124 Spider	01/2017-12/2019	315MHz		●	●	●	0/A	315Mhz	Continental	●	●
Abarth	124 Spider	10/2016-06/2020	433MHz		○	●	○	A	433Mhz	Continental	●	●
Acura	CSX	01/2008-12/2012	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	ILX	01/2016-12/2020	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	ILX	01/2013-12/2015	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	MDX	01/2004-12/2006	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	MDX	01/2018-12/2019	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Acura	MDX	01/2016-12/2019	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	MDX	06/2013-12/2015	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	MDX	01/2007-05/2013	315MHz		●	●	○	0/A	315Mhz	Pacific	●	●
Acura	NSX	01/2017-12/2020	315MHz		●	●	○	0	315MHz	Continental	●	●
Acura	NSX	01/2016-12/2019	433Mhz		●	●	○	0	433MHz	Continental	●	●
Acura	RDX	01/2018-12/2019	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Acura	RDX	01/2016-12/2020	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	RDX	01/2013-12/2015	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	RDX	01/2007-12/2012	315MHz		●	●	○	0/A	315Mhz	Pacific	●	●
Acura	RL	01/2009-12/2013	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	RL	01/2005-12/2008	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	RLX	01/2016-12/2020	315Mhz		●	●	○	0	315Mhz	Continental	●	●
Acura	RLX	01/2014-12/2015	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	TL	01/2005-12/2008	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	TL	01/2009-10/2012	315MHz		●	●	○	0	315Mhz	TRW	●	●
Acura	TL	11/2012-12/2014	315MHz		●	●	○	0/A	315Mhz	TRW	●	●
Acura	TLX	11/2014-12/2019	315MHz		●	●	○	0	315Mhz	Continental	●	●
Acura	TLX	01/2018-12/2020	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Acura	TSX	01/2009-12/2014	315MHz		●	●	○	0/A	315Mhz	Pacific	●	●
Acura	TSX	01/2007-12/2008	315MHz		●	●	○	0/A	315Mhz	Pacific	●	●
Acura	ZDX	01/2010-12/2015	315MHz		●	●	○	0	315Mhz	TRW	●	●
Alfa Romeo	159	07/2005-12/2013	433MHz	939	●	●	○	A	433Mhz	TRW	●	●
Alfa Romeo	4C	01/2012-12/2016	433Mhz	4C	●	●	●	0/A	433Mhz	Schrader	●	●
Alfa Romeo	4C	01/2017-06/2020	433Mhz		●	●	●	0/A	433Mhz	Schrader	●	●
Alfa Romeo	8C	12/2006-12/2010	433Mhz	920	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Alfa Romeo	Brera	01/2005-07/2012	433MHz	939/946	●	●	○	C	433Mhz	TRW	●	●
Alfa Romeo	Castello	01/2020-12/2020	433Mhz		○	●	○	C	433Mhz	Continental	●	●
Alfa Romeo	GTV	01/2020-12/2020	433Mhz		○	●	○	C	433Mhz	Continental	●	●
Alfa Romeo	Giulia	01/2016-06/2020	433Mhz		●	●	●	0/A	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Alfa Romeo	Giulietta	01/2014-06/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Alfa Romeo	MiTo	08/2013-06/2019	433MHz	955	●	●	○	O/A	433Mhz	Schrader	●	●
Alfa Romeo	MiTo	01/2008-07/2013	433MHz	955	●	●	○	O	433Mhz	TRW	●	●
Alfa Romeo	Spider	01/2006-12/2010	433MHz	939	○	●	○	C	433Mhz	TRW	●	●
Alfa Romeo	Stelvio	01/2017-06/2020	433Mhz		●	●	○	O/A	433Mhz	Continental	●	●
Alpina	Alpina 6	01/2018-06/2020	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Alpina	Alpina 7	04/2014-06/2020	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Alpina	Alpina 7	01/2011-03/2014	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Alpina	Alpina 7	01/2006-12/2008	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Alpina	Alpina 7	01/2004-12/2005	434MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Cygnat	01/2011-06/2018	433MHz		●	●	○	A	433Mhz	Pacific	●	●
Aston Martin	DB11	01/2016-06/2020	433Mhz	VH500	○	●	○	A	433Mhz	Schrader	●	●
Aston Martin	DB11	01/2016-06/2020	433Mhz (Huf)		○	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	DB11	01/2017-12/2019	315Mhz		○	●	○	A	315Mhz	Schrader	●	●
Aston Martin	DB9	01/2004-01/2018	433Mhz	AM803	●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	DB9	01/2005-12/2011	Smartire 433MHz		○	●	○	C	433Mhz	Smartire	●	●
Aston Martin	DB9	01/2010-12/2015	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Aston Martin	DBS	01/2018-06/2020	433MHz		●	●	○	C	433Mhz	Schrader	●	●
Aston Martin	DBS	09/2007-08/2012	433Mhz	AM803	●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	DBS Superleggera	01/2018-06/2020	433Mhz	VH500	○	●	○	A	433Mhz	Schrader	●	●
Aston Martin	DBX	10/2018-06/2020	SCH 433Mhz		●	●	○	A	433Mhz	Schrader	●	●
Aston Martin	One-77	01/2011-12/2012	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Rapide	01/2010-06/2020	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Rapide	01/2009-12/2019	315Mhz		●	●	○	A	315MHz	Huf/Beru	●	●
Aston Martin	Rapide S	01/2010-12/2019	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Rapide S	01/2014-12/2014	315Mhz		●	●	○	A	315MHz	Huf/Beru	●	●
Aston Martin	Vanquish	01/2010-12/2019	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Vantage	01/2005-12/2011	Smartire 433MHz		○	●	○	C	433Mhz	Smartire	●	●
Aston Martin	Vantage	01/2010-12/2019	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Virage	01/2011-12/2012	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Zagato	01/2011-08/2012	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A3	01/2006-12/2014	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	A3	01/2010-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A4	01/2002-12/2008	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A4	01/2013-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A4	01/2009-12/2012	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	A5	01/2007-12/2012	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	A5	01/2013-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A6	01/2002-12/2005	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	A6	01/2004-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6	01/2006-12/2011	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	A6	01/2010-12/2017	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	A6	01/2010-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6	01/2018-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Audi	A6 Allroad	01/2001-12/2005	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	A6 Allroad	04/2000-12/2005	433MHz	4B	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6 Allroad	01/2006-12/2011	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	A6 Allroad	01/2006-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6 Allroad	01/2010-12/2011	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6 Allroad	07/2017-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A6L	05/2004-05/2009	433MHz	4B	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6L	05/2004-05/2009	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Audi	A7	01/2009-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A7	01/2012-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A7 Quattro	01/2012-12/2016	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A8	01/2016-06/2020	433MHz 5Q0907275		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A8	01/2010-12/2015	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	A8	11/2009-10/2017	433MHz	4H/4L	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A8	10/2002-10/2009	433MHz	4E	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A8	01/1999-12/2009	315MHz	4E/4D	●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	A8	01/1999-09/2002	433MHz	4D	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A8	01/2013-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A9	01/2018-06/2020	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	Alltrack	01/2017-12/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q2	01/2015-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q2	01/2016-06/2020	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	Q3	01/2015-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q5	01/2017-12/2019	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	Q5	01/2010-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q5	01/2008-12/2015	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	Q7	01/2005-12/2012	315MHz		●	●	○	O/A	315Mhz	Huf/Beru	●	●
Audi	Q7	01/2013-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q7	01/2005-12/2009	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Audi	Q7	01/2010-12/2015	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Audi	Q8	01/2018-06/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q8	01/2018-06/2020	433MHz	4M	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	R8	01/2016-12/2019	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	R8	01/2010-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	R8	01/2008-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	R8 Race Car	01/2013-12/2014	315MHz		●	●	○	C	315Mhz	Huf/Beru	●	●
Audi	RS3	10/2016-12/2019	433MHz	8V	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS3	01/2017-12/2018	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
Audi	RS4	01/2018-06/2020	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS4	01/2007-12/2017	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS5	01/2012-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS5	01/2017-12/2019	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS6	01/2000-12/2005	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS6	01/2000-12/2005	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	RS6	01/2013-12/2017	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Audi	RS7	01/2013-12/2018	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	RS7	01/2014-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	S3	01/2015-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S4	01/2010-12/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S4	01/2010-12/2014	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	S4	01/2002-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	S4	01/2002-12/2003	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	S5	01/2008-12/2014	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Audi	S5	01/2018-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S5	01/2010-12/2017	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S6	01/2010-12/2019	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	S6	01/2010-12/2019	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Audi	S6	01/2004-12/2009	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Audi	S7	01/2017-06/2020	433MHz		●	●	○	C	433Mhz	Huf/Beru	●	●
Audi	S8	01/1999-09/2002	315MHz	D2	●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	S8	01/2018-12/2018	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	S8	11/2009-12/2018	433MHz	D4	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	S8	01/2012-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S8	10/2002-10/2009	433MHz	D3	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	S8	10/2002-10/2009	315MHz	D3	●	●	○	A	315Mhz	Huf/Beru	●	●
Audi	S8	01/1999-09/2002	433MHz	D2	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	SQ5	01/2014-06/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	SQ5	01/2014-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	SQ7	01/2016-12/2017	315MHz		●	●	○	O/A	315Mhz	Huf/Beru	●	●
Audi	TT	01/2007-12/2014	315MHz		●	●	○	A	315Mhz	Continental	●	●
Audi	TT	01/2010-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	TT RS	01/2018-12/2018	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	TTS	01/2009-12/2009	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	TTS	01/2012-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	e-tron	11/2018-06/2020	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
BMW	1 Series	01/2007-09/2010	433MHz	E88/E82	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	1 Series	10/2010-12/2015	433MHz	F20	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	1 Series	01/2016-12/2019	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	1 Series	07/2010-06/2020	433MHz	F20/F21/F40	●	●	○	A	433Mhz	Continental	●	●
BMW	2 Series	01/2014-12/2014	HUF 433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	2 Series	01/2014-12/2016	VDO 433MHz	F45/F46	●	●	○	A	433Mhz	Continental	●	●
BMW	2 Series	01/2014-12/2019	433Mhz	F22/F23/F45/F46	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series	01/2007-08/2009	433MHz	E9x	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	3 Series	01/2000-12/2006	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	3 Series	01/1999-12/2002	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
BMW	3 Series	09/2009-12/2013	433MHz	E9x	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	3 Series	01/2014-12/2019	433Mhz	F31/F35	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series	10/2010-11/2013	433MHz	F30	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	3 Series GT	03/2014-12/2019	433MHz	F34	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series GT	01/2013-02/2014	433MHz	F34	●	●	○	O/A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	3 Series Sedan	01/2013-02/2014	433MHz	F31/F32/F34	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	3 Series Sedan	01/2010-12/2012	433MHz	E9x	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	3 Series Sedan	03/2014-12/2019	433MHz	F34	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series Wagon	03/2014-12/2019	433MHz	F34	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series Wagon	01/2013-02/2014	433MHz	F31/F32/F34	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	4 Series	03/2014-06/2020	F32/F33/F36 433MHz	F32/F33/F36	●	●	○	A	433Mhz	Continental	●	●
BMW	4 Series	01/2005-02/2014	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series	01/2000-12/2001	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	5 Series	01/2002-12/2005	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
BMW	5 Series	03/2014-12/2017	433MHz	F10/F11	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series	01/2017-12/2019	433Mhz	G30/G31/G38	●	●	○	A	433Mhz	Schrader	●	●
BMW	5 Series	01/2006-09/2010	433MHz	E60/E61	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	5 Series	01/2002-12/2005	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	5 Series	10/2010-02/2015	433MHz	F10/F07/F18	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series	03/2014-12/2016	433Mhz	F10/F11/F18	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series	01/1997-12/2001	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
BMW	5 Series GT	01/2017-12/2019	433Mhz	G32	●	●	○	A	433Mhz	Schrader	●	●
BMW	5 Series GT	04/2014-06/2018	433MHz	F07 LCI	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series GT	01/2011-12/2016	433MHz	F10/F07	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series GT	01/2009-12/2010	433MHz	E60/E61	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	6 Series	04/2014-12/2019	433MHz	F12/F13/F06	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	6 Series	01/2011-03/2014	433MHz	F06/F12/F13	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	6 Series	09/2016-06/2020	433Mhz G14/G32	G14/G32	●	●	○	A	433Mhz	Schrader	●	●
BMW	6 Series	01/2003-12/2010	433MHz	E63/E64	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	7 Series	01/2002-12/2005	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	7 Series	03/2014-05/2015	433Mhz	F01/F02	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	7 Series	01/1999-12/2002	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
BMW	7 Series	01/1994-12/2001	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	7 Series	10/2010-12/2014	433MHz	F01/F02/F04	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	7 Series	06/2015-06/2020	433Mhz	G11/G12	●	●	○	A	433Mhz	Schrader	●	●
BMW	7 Series	01/2006-09/2010	433MHz	E65/E66	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	8 Series	10/2017-06/2020	433Mhz	G15	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	M1	01/2011-12/2012	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M2	11/2014-12/2019	433MHz	F87	●	●	○	A	433Mhz	Continental	●	●
BMW	M2	01/2017-12/2017	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M3	01/2002-12/2003	433Mhz		●	●	○	C	433Mhz	Huf/Beru	●	●
BMW	M3	01/2014-12/2018	433Mhz	F80	●	●	○	A	433Mhz	Continental	●	●
BMW	M3	01/2008-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	M3	01/2010-12/2013	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M4	01/2015-12/2019	433Mhz	F82/F83	●	●	○	A	433Mhz	Continental	●	●
BMW	M5	01/2016-12/2019	433Mhz	F90	●	●	○	A	433Mhz	Schrader	●	●
BMW	M5	04/2014-12/2018	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M5	09/2010-03/2014	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M5	01/2006-08/2010	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	M5	01/2002-12/2003	433Mhz		●	●	○	C	433Mhz	Huf/Beru	●	●
BMW	M6	01/2006-05/2011	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	M6	06/2011-12/2015	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M6	01/2016-12/2018	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	Motorcycle	01/2010-12/2019	433MHz		○	●	○	C	433Mhz	Schrader	●	●
BMW	Urban Cross	01/2020-06/2020	433MHz		○	●	○	C	433Mhz	Continental	●	●
BMW	X1	09/2008-02/2014	433MHz	E84	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X1	01/2016-12/2019	433Mhz	F48/F49	●	●	○	A	433Mhz	Continental	●	●
BMW	X1	03/2014-12/2016	433Mhz	E84	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X2	01/2016-12/2019	433MHz		●	●	○	A	433Mhz	Continental	●	●
BMW	X3	01/2006-04/2011	433MHz	E83	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X3	11/2010-03/2014	433MHz	F25	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X3	04/2014-12/2017	433Mhz	F25	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X3	01/2017-06/2020	G01/G08 433MHz		●	●	○	A	433Mhz	Schrader	●	●
BMW	X4	01/2014-12/2019	433Mhz	F26	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X4	03/2017-06/2020	433Mhz	G02	●	●	○	A	433Mhz	Schrader	●	●
BMW	X5	05/2013-12/2019	433Mhz	F15/F85	●	●	○	A	433Mhz	Continental	●	●
BMW	X5	09/2017-06/2020	433MHz	G05	●	●	○	A	433Mhz	Schrader	●	●
BMW	X5	01/2000-12/2005	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X5	01/2006-09/2010	433MHz	E70	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X5	10/2010-12/2013	433MHz	E70/F15	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X6	01/2015-12/2019	433MHz	F16/F86	●	●	○	A	433Mhz	Continental	●	●
BMW	X6	01/2010-12/2014	433MHz	E71	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X6	01/2007-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X6	01/2008-04/2011	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X6 HYBRID	01/2009-12/2011	433MHz	E71	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X7	01/2018-12/2019	433Mhz	G02	●	●	○	A	433Mhz	Schrader	●	●
BMW	Z Series	01/2015-12/2017	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	Z Series	10/2010-12/2014	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	Z Series	01/2006-09/2010	433MHz	E85/E86/E89	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	Z4	09/2010-02/2014	433MHz	E89/E71	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	Z4	03/2019-06/2020	433Mhz	G02	●	●	○	A	433Mhz	Schrader	●	●
BMW	Z4	03/2006-08/2010	433MHz	E86/E89	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	Z4	03/2014-02/2019	433MHz	E89	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	i Series	01/2014-06/2020	433MHz		●	●	○	A	433Mhz	Continental	●	●
BMW	i3	01/2013-12/2019	433Mhz	I01/I12	●	●	○	A	433Mhz	Continental	●	●
BMW	i8	01/2013-12/2019	433MHz	I01/I12	●	●	○	A	433Mhz	Continental	●	●
Bentley	Arnage	01/2008-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Azure	01/2007-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Azure	01/2010-12/2015	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Bentayga	01/2017-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Bentayga	01/2015-12/2016	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Brooklands	01/2008-12/2011	433Mhz		●	●	○	C	433Mhz	Huf/Beru	●	●
Bentley	Brooklands Coupe	01/2008-06/2016	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental	01/2005-05/2005	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Bentley	Continental	06/2005-12/2005	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental	01/2006-12/2011	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental	01/2012-12/2018	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental	01/2003-12/2004	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental Flying Spur	01/2009-12/2011	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Bentley	Continental GT	09/2003-05/2005	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental GT	06/2005-06/2020	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Continental GT	01/2010-01/2014	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Bentley	Continental GT	01/2005-12/2005	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Bentley	Flying Spur	01/2011-12/2015	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Bentley	Flying Spur	01/2005-12/2010	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Bentley	Flying Spur	01/2005-12/2010	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Flying Spur	01/2011-12/2018	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	GTC	07/2006-06/2020	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Mulsanne	01/2017-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Mulsanne	01/2011-12/2012	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Mulsanne	01/2009-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Mulsanne	01/2013-12/2015	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bentley	Mulsanne	01/2012-12/2012	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Bentley	Mulsanne	01/2016-12/2016	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Bugatti	Chiron	01/2016-06/2020	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Bugatti	Royale	01/2016-12/2019	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Bugatti	Veyron	01/2005-12/2015	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Buick	Allure	01/2010-12/2010	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Allure	01/2011-12/2015	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Buick	Allure	01/2006-12/2007	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Buick	Allure	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Buick	Allure	01/2008-12/2009	315MHz 13598771		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Allure	01/2009-12/2009	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Allure	01/2006-12/2006	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	Cascada	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Cascada	01/2017-12/2019	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Cascada	01/2018-12/2019	433MHz		○	●	○	S	433MHz	Schrader	●	●
Buick	Century	01/1999-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	Enclave	01/2017-12/2017	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Buick	Enclave	01/2016-12/2016	315Mhz		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Enclave	06/2014-12/2016	315MHz 23445327		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Enclave	01/2019-06/2020	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Buick	Enclave	09/2013-12/2015	315MHz 25920615		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Enclave	01/2013-08/2013	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Buick	Enclave	01/2009-08/2013	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Buick	Enclave	05/2007-12/2008	315MHz		●	●	●	0/S	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Buick	Enclave	09/2013-12/2016	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Buick	Enclave	01/2017-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Enclave	01/2018-12/2018	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Buick	Encore	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Encore	01/2018-06/2020	315MHz		○	●	○	S	315MHz	Schrader	●	●
Buick	Encore	01/2017-12/2017	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Encore	01/2013-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Envision	01/2016-06/2020	315MHz 13516164		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Envision	01/2016-12/2017	315MHz 13598772		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Envision	01/2015-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Envision	01/2019-12/2019	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2017-12/2019	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2017-12/2019	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
Buick	LaCrosse	01/2009-10/2009	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2014-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2013-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2011-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	11/2009-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2007-12/2007	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Buick	LaCrosse	01/2006-12/2006	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2008-12/2009	315MHz 13898771		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2012-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	LaCrosse	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Buick	LaCrosse	01/2008-12/2008	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	LaCrosse	01/2016-12/2016	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Buick	LeSabre	01/1998-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	LeSabre	01/2007-12/2007	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Buick	Lucerne	01/2006-12/2006	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	Lucerne	01/2007-12/2007	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Lucerne	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Lucerne	01/2009-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Park Avenue	01/2009-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Park Avenue	01/1997-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	Park Avenue	01/2006-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Rainier	01/2007-12/2007	Snap in 315MHz		●	●	●	S	315Mhz	Schrader	●	●
Buick	Rainier	01/2006-12/2009	Clamp in 315MHz		●	●	●	S	315Mhz	Schrader	●	●
Buick	Rainier	01/2006-12/2006	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Buick	Regal	01/1997-12/2004	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	Regal	05/2009-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Regal	01/2013-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Regal	01/2014-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Buick	Regal	01/2017-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Regal	08/2017-06/2020	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Buick	Regal	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Rendezvous	01/2003-12/2007	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Buick	Verano	01/2012-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Verano	01/2016-12/2019	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Buick	Verano	01/2013-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
CMC	A180	07/2016-12/2019	433MHz		●	●	○	O	433Mhz	Orange Electronic	●	●
CMC	A190	07/2016-12/2019	433MHz		●	●	○	O	433Mhz	Orange Electronic	●	●
CMC	VERYCA	07/2016-06/2019	433MHz		●	●	○	C	433Mhz	Schrader	●	●
CMC	ZINGER	07/2016-06/2019	433MHz		●	●	○	C	433Mhz	Schrader	●	●
Cadillac	ATS	01/2013-12/2013	315Mhz		●	●	●	O/S	315Mhz	Continental	●	●
Cadillac	ATS	01/2016-12/2017	315MHz 13598786		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ATS	01/2015-12/2017	315MHz 13598772		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ATS	01/2018-12/2019	315MHz 13598772		○	●	○	S	315MHz	Schrader	●	●
Cadillac	ATS	01/2018-12/2019	315MHz 13598786		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	ATS	01/2015-12/2015	315MHz 20964159		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ATS	01/2013-12/2014	315MHz 13581558		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ATS	01/2018-12/2018	433Mhz		○	●	○	S	433Mhz	Schrader	●	●
Cadillac	ATS	01/2016-12/2017	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	ATS	01/2013-12/2014	315MHz 20964159		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ATS Sport	01/2014-12/2015	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	ATS-L	01/2014-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ATS-V	01/2016-12/2019	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Cadillac	ATS-V	01/2018-12/2019	315MHz 13598772		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	ATS-V	01/2018-12/2019	315MHz 13598786		○	●	○	S	315MHz	Schrader	●	●
Cadillac	ATS-V	01/2013-12/2015	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	ATS-V	01/2016-12/2016	315Mhz		○	●	○	S	315Mhz	Continental	●	●
Cadillac	ATS-V	01/2016-12/2017	315MHz 13598786		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	CT5	01/2020-12/2020	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	CT6	01/2016-12/2018	315Mhz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	CT6	01/2019-06/2020	433MHz 13516165		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	CT6	01/2016-12/2019	433Mhz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	CT6	01/2019-06/2020	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2016-12/2019	315MHz 13598786		●	●	●	O/S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Cadillac	CTS	01/2016-12/2019	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	01/2016-12/2019	433MHz 13598787		●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	CTS	01/2014-12/2015	315MHz 20964159		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2014-12/2015	315MHz 13581558		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2013-12/2013	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2014-12/2014	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2008-12/2008	433Mhz	GMX206/ GMX226	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	CTS	01/2004-12/2005	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2006-12/2006	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2007-09/2007	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	10/2007-12/2008	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2014-12/2014	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2009-12/2009	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2009-12/2009	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2010-12/2011	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2010-12/2011	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2012-12/2012	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2012-12/2012	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS	01/2013-12/2013	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS-V	01/2018-12/2019	315MHz		○	●	○	S	315MHz	Schrader	●	●
Cadillac	CTS-V	01/2017-12/2019	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Cadillac	CTS-V	01/2017-12/2017	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	CTS-V	01/2016-12/2016	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Cadillac	CTS-V	01/2014-12/2016	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	CTS-V	01/2009-12/2013	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	CTS-V (Sport)	01/2014-12/2014	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	CTS-V (Sport)	01/2015-12/2016	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	CTS-V (Sport)	01/2017-12/2019	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	DTS	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	DTS	01/2006-12/2006	315MHz 25920615		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	DTS	01/2009-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	DTS	01/2007-12/2007	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Cadillac	DTS	01/2005-12/2006	315MHz 15268606		○	●	○	S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Cadillac	Deville	01/2005-12/2005	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Cadillac	Deville	01/2000-12/2003	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Cadillac	Deville	01/2004-12/2004	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Cadillac	ELR	01/2014-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	ELR	01/2017-12/2018	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	ELR	01/2016-12/2016	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	Escalade	01/2015-12/2016	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2014-12/2014	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2004-12/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2005-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2007-12/2007	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2007-12/2007	Clamp in 315MHz		●	●	●	O/S	315Mhz	TRW	●	●
Cadillac	Escalade	01/2009-12/2011	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2010-12/2011	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2012-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2013-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Escalade	01/2018-12/2019	433Mhz 13516165		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	Escalade	01/2017-06/2020	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	01/2015-12/2018	433Mhz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	Hearse	01/2001-12/2005	315MHz		●	●	○	C	315Mhz	Schrader	●	●
Cadillac	Limousine	01/2001-12/2005	315MHz		●	●	○	C	315Mhz	Schrader	●	●
Cadillac	SLS	01/2012-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SLS	01/2010-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SLS	01/2009-12/2009	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SLS	01/2006-12/2008	315MHz		●	●	○	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	01/2015-12/2016	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	SRX	01/2004-12/2006	315MHz		●	●	○	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	01/2005-12/2006	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
Cadillac	SRX	01/2009-12/2009	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	01/2010-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	01/2012-09/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	01/2007-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	10/2012-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	SRX	10/2014-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	STS	01/2009-12/2009	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	STS	01/2009-12/2009	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	STS	01/2008-12/2008	315MHz		●	●	○	O/S	315Mhz	Schrader	●	●
Cadillac	STS	01/2004-12/2007	315MHz		●	●	○	O/S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Cadillac	STS	01/2011-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	STS	01/2010-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	Seville	01/2004-12/2004	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Cadillac	Seville	01/2001-12/2003	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Cadillac	XLR	01/2006-12/2009	315MHz		●	●	○	O/S	315Mhz	Schrader	●	●
Cadillac	XLR	01/2004-12/2005	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	XLR	01/2010-12/2011	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Cadillac	XLR-V	01/2006-12/2008	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Cadillac	XT4	01/2019-06/2020	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	XT5	01/2018-06/2020	315MHz 13516164		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	XT5	01/2017-12/2019	315MHz 13589597		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	XT5	01/2016-12/2018	433Mhz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	XT5	01/2018-06/2020	433MHz 13516165		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	XT6	01/2019-06/2020	433MHz		○	●	○	C	433Mhz	Schrader	●	●
Cadillac	XTS	01/2017-12/2019	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	XTS	01/2013-12/2014	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	XTS	01/2015-12/2015	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	XTS	01/2015-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Cadillac	XTS	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2005-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2007-12/2007	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2007-12/2007	Clamp in 315MHz		●	●	●	O/S	315Mhz	TRW	●	●
Chevrolet	Avalanche	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2009-12/2011	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2010-12/2011	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2012-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Avalanche	01/2004-12/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Aveo	01/2002-12/2007	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Chevrolet	Aveo	01/2008-12/2010	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Chevrolet	Aveo	01/2011-12/2011	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Chevrolet	Aveo	01/2012-12/2012	315MHz		●	●	●	O	315Mhz	Schrader	●	●
Chevrolet	Aveo	01/2018-12/2018	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Chevrolet	Blazer	01/2019-06/2020	433MHz		○	●	●	S	433Mhz	Schrader	●	●
Chevrolet	Bolt EV	01/2019-06/2020	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Bolt EV	01/2017-06/2020	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Bolt EV	01/2017-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2012-12/2013	315MHz 20964159		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2012-12/2013	433MHz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Camaro	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2013-12/2013	315MHz 12768826		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2014-12/2015	315MHz 20964159		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2010-12/2011	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	01/2014-12/2015	315MHz 22854866		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2014-12/2015	433MHz 13598773		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	01/2016-12/2016	Clamp in 433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	01/2017-12/2019	Snap in 433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	01/2016-12/2016	Snap in 433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	01/2018-12/2019	315MHz 13598786		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2017-12/2019	Clamp in 433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	01/2010-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro	01/2012-12/2012	315MHz 12768826		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro ZL1	01/2012-12/2013	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro ZL1	01/2014-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro ZL1	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Camaro ZL1	01/2017-12/2019	433MHz 13598787		○	●	○	S	433MHz	Schrader	●	●
Chevrolet	Camaro ZL1	01/2017-12/2019	433MHz 13598773		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Caprice	01/2011-12/2013	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Caprice	01/2014-12/2017	315MHz 13581559		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Caprice	01/2016-12/2017	315MHz 13598786		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Caprice	01/2017-12/2019	315MHz 13598772		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Captiva	01/2012-12/2015	315MHz Clamp in		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Captiva	12/2012-12/2019	315MHz Snap in		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Cavalier	01/2016-06/2020	Hi Line 433MHz		●	●	○	S	433Mhz	DIAS	●	●
Chevrolet	Cavalier	01/2016-06/2020	Lo Line 433MHz		○	●	○	C	433Mhz	DIAS	●	●
Chevrolet	Cheyenne	11/2016-12/2019	315MHz		●	●	●	0	315MHz	Schrader	●	●
Chevrolet	Cheyenne	01/2016-12/2018	433MHz 13598773		●	●	●	0	433Mhz	Schrader	●	●
Chevrolet	Cheyenne	01/2018-06/2020	433MHz 13516165		●	●	●	0	433Mhz	Schrader	●	●
Chevrolet	Cheyenne	01/2007-12/2013	Snap in 315MHz		○	●	○	C	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Cheyenne	01/2010-12/2011	Clamp in 315MHz		○	●	○	C	315Mhz	Schrader	●	●
Chevrolet	Cheyenne	01/2014-12/2014	315MHz		●	●	●	O	315Mhz	Schrader	●	●
Chevrolet	Cheyenne	01/2015-10/2016	315MHz		●	●	●	O	315Mhz	Schrader	●	●
Chevrolet	Cheyenne DRW	01/2015-12/2016	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Chevrolet	Cheyenne DRW	01/2017-12/2019	433Mhz		○	●	○	C	433Mhz	Schrader	●	●
Chevrolet	Cheyenne DRW	01/2017-12/2019	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Chevrolet	City Express	01/2015-12/2018	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Chevrolet	Cobalt	01/2010-12/2010	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Cobalt	01/2009-12/2009	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Cobalt	01/2008-12/2008	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Cobalt	01/2008-12/2008	Clamp in 315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Chevrolet	Cobalt	01/2009-12/2009	Clamp in 315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Chevrolet	Cobalt	01/2010-12/2010	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2007-12/2010	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2011-12/2011	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2017-12/2019	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2015-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2014-12/2014	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2012-12/2012	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Colorado	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2013-12/2013	315MHz	C6	●	●	○	O/S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2014-12/2014	433MHz	C7	●	●	●	O/A	433Mhz	Schrader	●	●
Chevrolet	Corvette	01/2015-12/2019	433MHz	C7	●	●	●	O/S/A	433Mhz	Schrader	●	●
Chevrolet	Corvette	01/2016-12/2019	315MHz 13581559	C7	●	●	●	O/S/A	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/1997-12/2000	315MHz	C5	○	●	○	S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2014-12/2019	315MHz 40700JA01B	C7	●	●	●	O/S/A	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2001-12/2002	315MHz	C5	●	●	○	S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2003-12/2004	315MHz	C5	●	●	○	S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2005-12/2009	315MHz 25758220	C6	●	●	○	O/S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2009-12/2009	315MHz 13598771	C6	●	●	○	O/S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2010-12/2011	315MHz	C6	●	●	○	O/S	315Mhz	Schrader	●	●
Chevrolet	Corvette	01/2010-12/2014	433MHz	C6	●	●	○	O/S	433Mhz	Schrader	●	●
Chevrolet	Corvette	01/2012-12/2012	315MHz	C6	●	●	○	O/S	315Mhz	Schrader	●	●
Chevrolet	Corvette Grand	01/2017-12/2018	315MHz		●	●	●	O/A	315Mhz	Schrader	●	●
Chevrolet	Cruze	01/2019-12/2020	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Cruze	01/2019-06/2020	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Cruze	01/2011-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Cruze	01/2012-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Cruze	01/2013-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Cruze	01/2016-12/2019	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Cruze	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Cruze	01/2017-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2011-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2010-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2009-12/2009	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2007-12/2007	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2013-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2017-05/2017	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	06/2017-06/2020	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Equinox	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Equinox	01/2013-12/2014	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Express Series	01/2010-12/2011	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Express Series	01/2016-12/2017	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Express Series	01/2017-12/2017	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Express Series	01/2018-06/2020	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Chevrolet	Express Series	01/2018-06/2020	315MHz		○	●	○	S	315MHz	Schrader	●	●
Chevrolet	Express Series	01/2014-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Express Series	01/2012-12/2013	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Express Series	01/2009-12/2009	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Chevrolet	Express Series	06/2007-12/2008	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Chevrolet	G Series	01/2008-12/2008	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Chevrolet	HHR	01/2008-12/2008	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	HHR	01/2010-12/2011	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	HHR	01/2009-12/2009	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	HHR	01/2009-12/2010	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	HHR	01/2008-12/2008	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2015-12/2016	Limited 315Mhz 13598771		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2015-12/2016	Limited 315MHz 23445327		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2016-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2016-06/2020	433MHz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Impala	01/2017-12/2018	315MHz 23445327		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2017-06/2020	315MHz 13598772		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2020-06/2020	433MHz 13516165		●	●	●	O/S	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Impala	01/2020-06/2020	315MHz 13516164		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2000-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Chevrolet	Impala	01/2006-12/2006	Clamp in 315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Impala	01/2006-12/2006	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2007-12/2007	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2007-12/2007	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2009-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2012-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2013-09/2013	315MHz 22854866		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2013-09/2013	315MHz 13598771		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	10/2013-12/2014	315MHz 22854866		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Impala	10/2013-12/2014	Limited 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2019-06/2020	315MHz 13516164		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2008-12/2008	Clamp in 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Chevrolet	Malibu	01/2008-12/2008	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2009-12/2009	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2019-06/2020	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	01/2017-12/2019	315MHz 22854866		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2017-12/2018	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	01/2016-12/2016	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	01/2016-12/2016	315Mhz 23445327		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2016-12/2016	315MHz 25920615		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	07/2014-12/2015	433MHz	V300	●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	01/2010-06/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	07/2011-06/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	07/2011-06/2012	433MHz	V300	●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	07/2012-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	07/2012-12/2012	433MHz	V300	●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	01/2013-12/2013	315MHz 25920615		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Malibu	01/2013-06/2014	433MHz	V300	●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	01/2013-12/2014	315MHz 22854866		●	●	●	0/S	315Mhz	Schrader	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Malibu Fleet	01/2015-12/2015	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Malibu Fleet	01/2016-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Monte Carlo	01/2006-12/2006	315MHz		○	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Monte Carlo	01/2007-12/2007	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Monte Carlo	01/2007-12/2007	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Monte Carlo	01/2000-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Chevrolet	Onix	08/2014-12/2019	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Optra	01/2007-12/2009	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Chevrolet	Orlando	01/2017-12/2018	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Orlando	01/2013-12/2014	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Orlando	01/2012-12/2012	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Prisma	08/2014-12/2019	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	S10	01/2017-12/2019	433MHz		○	●	○	C	433Mhz	Schrader	●	●
Chevrolet	SS Sedan	01/2017-12/2017	315MHz 13581559		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	SS Sedan	01/2017-12/2018	315MHz 20964159		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	SS Sedan	01/2013-12/2016	315MHz 13581559		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	SS Sedan	01/2014-12/2016	315MHz 20964159		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	SSR	01/2006-12/2007	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Chevrolet	Silverado	10/2013-12/2014	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2009-09/2013	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2009-12/2011	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2007-12/2007	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2007-12/2007	Clamp in 315MHz		●	●	●	O/S	315Mhz	TRW	●	●
Chevrolet	Silverado	01/2005-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2004-12/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Silverado	01/2017-06/2020	433Mhz 13516165		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Silverado	01/2017-12/2018	433Mhz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Silverado	11/2016-12/2019	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Silverado	01/2015-12/2016	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Chevrolet	Silverado	01/2015-10/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Silverado DRW	01/2015-12/2016	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Chevrolet	Silverado DRW	01/2017-12/2019	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Chevrolet	Silverado DRW	01/2017-12/2019	433Mhz		○	●	○	S	433Mhz	Schrader	●	●
Chevrolet	Sonic	01/2017-06/2020	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Sonic	01/2015-12/2016	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Chevrolet	Sonic	01/2013-12/2014	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Sonic	01/2012-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Spark	01/2013-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Spark	01/2017-06/2020	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Spark	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Spark	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Spin	08/2014-12/2019	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Suburban	01/2014-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2009-12/2013	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2009-12/2013	clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2007-12/2007	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2007-12/2007	Clamp in 315MHz		●	●	●	0/S	315Mhz	TRW	●	●
Chevrolet	Suburban	01/2018-12/2019	433MHz 13516165		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Suburban	01/2004-12/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	09/2016-06/2020	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Suburban	01/2016-12/2018	433MHz 13598773		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Suburban	01/2016-08/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Suburban	01/2005-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2018-12/2019	433MHz 13516165		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2014-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2010-12/2011	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2017-06/2020	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Tahoe	01/2016-12/2018	433MHz 13598773		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2009-12/2013	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2007-12/2007	Clamp in 315MHz		●	●	●	0/S	315Mhz	TRW	●	●
Chevrolet	Tahoe	01/2007-12/2007	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2005-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2004-12/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Tahoe	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Trailblazer	01/2007-12/2009	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Trailblazer	01/2006-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2009-12/2013	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2013-12/2013	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Traverse	01/2014-12/2017	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Traverse	06/2014-12/2016	315Mhz 23445327		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2016-12/2016	315MHz 13581558		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2016-12/2017	315Mhz 13598771		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2018-12/2019	315Mhz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2014-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Traverse	01/2018-06/2020	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Trax	01/2017-06/2020	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Trax	01/2013-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Trax	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Trax	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Uplander	01/2008-12/2009	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Uplander	01/2008-12/2009	315MHz 13598771		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Van	01/2008-12/2011	315Mhz		○	●	○	S	315Mhz	Continental	●	●
Chevrolet	Volt	01/2016-12/2018	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Volt	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Volt	01/2013-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Volt	01/2017-06/2020	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Volt	01/2011-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Chevrolet	Volt	01/2010-12/2010	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Chrysler	200	01/2008-12/2014	315MHz		●	●	●	0/A	315Mhz	Continental	●	●
Chrysler	200	01/2012-12/2013	433MHz		●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	200	01/2014-12/2016	433MHz		●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	200	01/2017-12/2019	433MHz		●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	300	01/2007-12/2007	433MHz	LX	●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	300	01/2008-12/2008	433MHz	LX	●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	300	01/2005-12/2006	315MHz	LX	●	●	●	0/A	315Mhz	Continental	●	●
Chrysler	300	01/2009-12/2009	433MHz	LX	●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300	01/2007-12/2007	315MHz	LX	●	●	●	0/A	315Mhz	Continental	●	●
Chrysler	300	01/2010-12/2010	433MHz	LX	●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300	01/2011-12/2013	433MHz	LX	●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300	01/2014-12/2015	433MHz	LX	●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300	01/2016-12/2016	433MHz		●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300	01/2017-12/2017	433MHz		●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300	01/2018-06/2020	433MHz		●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300 SRT	01/2010-12/2012	433MHz		●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300 SRT	01/2013-06/2020	433MHz		●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300C	01/2006-12/2006	315MHz		●	●	●	0	315Mhz	Continental	●	●
Chrysler	300C	01/2014-12/2015	433MHz 56029400AE		●	●	●	0/A	433Mhz	Schrader	●	●
Chrysler	300C	01/2016-06/2019	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Chrysler	300C	06/2005-05/2010	433Mhz	LE48	●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	300M	01/2002-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Chrysler	Aspen	01/2012-12/2015	433MHz		○	●	○	C	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chrysler	Aspen	01/2008-12/2011	315MHz	HG	●	●	●	O/A	315Mhz	Schrader	●	●
Chrysler	Aspen	01/2007-12/2007	315MHz	HG	●	●	●	O/A	315Mhz	Continental	●	●
Chrysler	Concorde	01/2002-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Chrysler	Crossfire	01/2005-12/2006	315MHz	ZH	●	●	○	C	315Mhz	Continental	●	●
Chrysler	Crossfire	01/2009-12/2011	315MHz	ZH	●	●	○	O	315Mhz	Continental	●	●
Chrysler	Crossfire	01/2009-12/2011	433MHz	ZH	●	●	○	C	433Mhz	Schrader	●	●
Chrysler	Crossfire	01/2003-12/2008	433MHz	ZH	●	●	○	C	433Mhz	Schrader	●	●
Chrysler	Crossfire(International)	01/2007-12/2008	315MHz	ZH	●	●	○	C	315Mhz	Continental	●	●
Chrysler	Crossfire(International)	01/2007-12/2008	433MHz	ZH	●	●	○	C	433Mhz	Schrader	●	●
Chrysler	Crossfire(NAFTA)	01/2007-12/2008	315MHz	ZH	●	●	○	C	315Mhz	Continental	●	●
Chrysler	Crossfire(NAFTA)	01/2007-12/2008	433MHz	ZH	●	●	○	C	433Mhz	Schrader	●	●
Chrysler	Intrepid	01/2002-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Chrysler	PT Cruiser	11/2007-12/2010	315MHz	PT	●	●	●	O/A	315Mhz	Continental	●	●
Chrysler	Pacifica	01/2004-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Chrysler	Pacifica	01/2003-12/2003	433MHz		●	●	○	A	433Mhz	Schrader	●	●
Chrysler	Pacifica	01/2004-12/2005	315MHz		●	●	○	A	315Mhz	Continental	●	●
Chrysler	Pacifica	01/2006-12/2008	315MHz	CS	●	●	○	A	315Mhz	Continental	●	●
Chrysler	Pacifica	01/2017-06/2020	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Chrysler	Prowler	01/2002-12/2002	433MHz		●	●	○	C	433Mhz	Schrader	●	●
Chrysler	Sebring	01/2008-12/2011	315MHz	JS	●	●	●	O/A	315Mhz	Continental	●	●
Chrysler	Sebring	01/2007-12/2010	433MHz	JS	●	●	●	O/A	433Mhz	Continental	●	●
Chrysler	Sebring	01/2007-12/2007	315MHz	JS	●	●	●	O/A	315Mhz	Continental	●	●
Chrysler	Town & Country	01/2002-12/2003	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Chrysler	Town & Country	01/2004-12/2005	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Chrysler	Town & Country	01/2006-12/2010	315MHz		●	●	●	O/A	315Mhz	Continental	●	●
Chrysler	Town & Country	01/2007-12/2010	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Chrysler	Town & Country	01/2014-12/2015	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Chrysler	Town & Country	01/2016-12/2019	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Chrysler	Town & Country	01/2011-12/2013	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Chrysler	Voyager	01/2017-12/2020	433MHz		○	●	○	C	433Mhz	Continental	●	●
Chrysler	Voyager	01/2002-12/2003	433MHz		●	●	○	S	433Mhz	Schrader	●	●
DFM	MX6	01/2015-12/2016	QY1036 433Mhz		○	●	○	C	433Mhz	Baolong	●	●
DFM	ix5	01/2018-12/2019	433Mhz		●	●	○	O	433MHz	Schrader	●	●
Dodge	Avenger	01/2007-12/2009	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Avenger	01/2007-12/2014	315MHz		●	●	●	O/A	315Mhz	Continental	●	●
Dodge	C/V	01/2013-12/2014	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Dodge	C/V	01/2015-12/2016	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Dodge	C/V	01/2012-12/2012	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Dodge	Caliber	01/2007-12/2007	315MHz	PM	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Caliber	01/2011-12/2012	315MHz	PM	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Caliber	01/2010-12/2010	315MHz	PM	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Caliber	01/2008-12/2009	315MHz	PM	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Caravan	01/2004-12/2005	315MHz		●	●	○	O/A	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Dodge	Caravan	01/2002-12/2003	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
Dodge	Caravan	01/2006-06/2010	315MHz		●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Challenger	01/2017-12/2018	433MHz		●	●	●	0	433Mhz	Schrader	●	●
Dodge	Challenger	01/2019-12/2019	433MHz		●	●	●	0	433Mhz	Schrader	●	●
Dodge	Challenger	01/2009-12/2009	433MHz	LC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Challenger	01/2008-12/2008	433MHz	LC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Challenger	01/2016-12/2016	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Challenger	01/2010-12/2010	433MHz	LC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Challenger	01/2011-12/2013	433MHz	LC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Challenger	01/2014-12/2015	433MHz	LC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Challenger SRT	01/2015-06/2020	433MHz	LD	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2005-12/2006	315MHz	LX	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Charger	01/2008-12/2008	433MHz	LX	●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Charger	01/2009-12/2009	433MHz	LX	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2010-12/2010	433MHz	LX	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2011-12/2013	433MHz	LD	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2016-12/2016	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2014-12/2015	433MHz	LD	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2007-12/2007	315MHz	LX	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Charger	08/2017-06/2020	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger	01/2017-07/2017	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger SRT	01/2010-12/2010	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger SRT	01/2009-12/2009	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Charger SRT	01/2016-06/2020	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Dakota	01/2008-12/2010	Snap in 315MHz	ND	●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Dakota	01/2008-12/2010	Clamp in 315MHz	ND	●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Dakota	01/2011-12/2011	315MHz	ND	●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Dart	10/2012-12/2017	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Durango	01/2007-12/2008	315MHz	HB	●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Durango	01/2016-12/2017	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Durango	01/2014-12/2015	433MHz	WD	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Durango	01/2011-12/2013	433MHz	WD	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Durango	01/2009-12/2010	315MHz	HB	●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Durango	01/2018-06/2020	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Durango SRT	01/2018-06/2020	433MHz		●	●	●	A	433Mhz	Continental	●	●
Dodge	Grand Caravan	01/2016-12/2016	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Grand Caravan	01/2017-06/2020	433MHz		●	●	●	0	433Mhz	Schrader	●	●
Dodge	Grand Caravan	01/2011-12/2013	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Grand Caravan	01/2014-12/2015	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Grand Caravan	01/2002-12/2003	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
Dodge	Grand Caravan	01/2004-12/2005	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Dodge	Grand Caravan	01/2006-12/2007	315MHz		●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Grand Caravan	01/2008-12/2010	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Intrepid	01/2002-12/2004	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Dodge	Journey	10/2016-10/2017	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Journey	01/2014-09/2016	433MHz	JC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Journey	01/2011-12/2013	433MHz	JC	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Journey	01/2010-12/2010	Hi line 433Mhz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Journey	01/2010-12/2010	Lo Line 433Mhz	JC	●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Journey	01/2009-12/2009	433MHz	JC	●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Journey	11/2017-12/2019	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Magnum	01/2010-12/2010	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Magnum	01/2008-12/2008	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Dodge	Magnum	01/2007-12/2007	315MHz		●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Magnum	01/2005-12/2006	315MHz		●	●	●	O/A	315Mhz	Continental	●	●
Dodge	Magnum	01/2011-12/2011	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Magnum	01/2009-12/2009	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Nitro	01/2009-12/2012	315MHz	KA	●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Nitro	11/2006-12/2008	315MHz	KA	●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Nitro	06/2006-12/2012	433MHz	KA	●	●	●	0	433Mhz	Schrader	●	●
Dodge	RAM Power Wagon	01/2017-06/2019	433MHz		●	●	●	0	433Mhz	TRW	●	●
Dodge	RAM Rebel	01/2016-12/2019	433MHz		●	●	●	0	433Mhz	TRW	●	●
Dodge	Ram Cargo	01/2015-12/2015	433Mhz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Ram Promaster	01/2014-06/2020	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Ram Promaster City	01/2015-12/2019	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Ram Series	01/2009-12/2010	SCH Old 433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Ram Series	10/2015-12/2017	DRW 433MHz		●	●	●	A	433Mhz	TRW	●	●
Dodge	Ram Series	01/2007-12/2009	315MHz		●	●	●	O/A	315Mhz	Schrader	●	●
Dodge	Ram Series	01/2010-12/2013	SCH New 433MHz	D2	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	Ram Series	01/2019-06/2020	DT 433Mhz 68293199AA		●	●	○	O/A	433Mhz	Schrader	●	●
Dodge	Ram Series	10/2013-12/2017	433MHz		●	●	●	O/A	433Mhz	TRW	●	●
Dodge	Ram Series	01/2018-06/2020	433MHz		●	●	●	O/A	433Mhz	TRW	●	●
Dodge	Ram Series DRW	01/2018-12/2019	433MHz Steel wheel		○	●	○	A	433Mhz	TRW	●	●
Dodge	Ram Series DRW	01/2018-12/2019	433MHz Alloy wheel		○	●	○	A	433Mhz	TRW	●	●
Dodge	Ram Series DRW	01/2014-12/2017	433MHz Alloy wheel		●	●	○	O/A	433Mhz	TRW	●	●
Dodge	Ram Series DRW	01/2014-12/2017	433MHz Steel wheel		●	●	○	O/A	433Mhz	TRW	●	●
Dodge	SRT Viper	01/2016-06/2019	433MHz		●	●	●	0	433Mhz	Schrader	●	●
Dodge	Sprinter	01/2007-12/2013	315MHz	VB	●	●	○	O/A	315Mhz	Continental	●	●
Dodge	Stratus	01/2007-12/2007	315MHz	JR	●	●	○	O/A	315Mhz	Continental	●	●
Dodge	Viper	01/2003-12/2011	433MHz	ZB	○	●	○	C	433Mhz	Schrader	●	●
Dodge	viper	01/2013-12/2016	433MHz	VX	●	●	●	O/A	433Mhz	Schrader	●	●
Dodge	viper	01/2017-12/2019	433MHz		●	●	●	0	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ferrari	458 Italia	01/2014-12/2016	433Mhz	F142	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	458 Italia	01/2009-12/2013	433Mhz	F142	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	458 Speciale	01/2013-12/2016	433Mhz	F142	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	458 Spider	09/2009-12/2019	433Mhz	F142	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	488	01/2015-06/2020	433Mhz	F142	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	550 Maranello	01/2010-12/2012	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	550 Maranello	01/1998-12/2002	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	575M Maranello	01/2002-12/2006	315MHz		○	●	○	C	315Mhz	Huf/Beru	●	●
Ferrari	575M Maranello	01/2002-12/2006	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	599 GTB	01/2004-12/2014	433MHz	F141	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	599 GTO	01/2004-12/2012	433MHz	F141	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	599 SA Aperta	01/2004-12/2012	433MHz	F141	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	612 Scaglietti	01/2004-12/2012	433MHz	F137	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	812 Superfast	01/2017-12/2019	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Ferrari	California	01/2008-12/2014	433MHz	F149	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	California	01/2015-06/2019	433MHz	F149	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	Enzo	01/2003-12/2009	433MHz	F140	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	F12 Berlinetta	10/2012-12/2017	433Mhz	F151/ F152	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	F12 Berlinetta	10/2012-12/2014	315MHz	F151/ F152	●	●	○	O/A	315Mhz	Huf/Beru	●	●
Ferrari	F12 tdf	01/2015-12/2018	433Mhz	F151/ F152	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	F430	01/2005-12/2007	433MHz	F131E	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	F430	01/2008-12/2011	433MHz	F131E	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	F588 Dino	01/2019-12/2020	433MHz		○	●	○	C	433Mhz	Huf/Beru	●	●
Ferrari	FF	01/2011-06/2019	433Mhz	F151	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Ferrari	FF	01/2011-06/2019	315MHz	F151	●	●	○	O/A	315Mhz	Huf/Beru	●	●
Ferrari	FXX	01/2003-12/2009	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	GTC4 Lusso	01/2016-12/2019	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	La Ferrari	01/2014-12/2019	433MHz	F150	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	Portofino	01/2016-12/2019	433MHz		○	●	○	C	433Mhz	Huf/Beru	●	●
Ferrari	Spider	01/2002-12/2009	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Fiat	124 Spider	01/2016-06/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500	01/2017-12/2019	433MHz		●	●	●	O	433Mhz	Schrader	●	●
Fiat	500	01/2014-12/2016	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Fiat	500	01/2011-12/2013	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Fiat	500C	01/2015-12/2017	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Fiat	500E	01/2015-12/2017	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Fiat	500L	03/2013-12/2016	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Fiat	500L	01/2017-12/2019	433MHz		●	●	●	O	433Mhz	Schrader	●	●
Fiat	500X	01/2014-12/2016	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Fiat	500X	01/2017-06/2020	433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Ford	C-Max	01/2014-12/2016	315MHz	C344N	●	●	●	O/S	315Mhz	Schrader	●	●
Ford	C-Max	01/2013-12/2013	315MHz	C344N	●	●	●	S	315Mhz	Schrader	●	●
Ford	C-Max	01/2017-12/2019	315MHz		●	●	●	S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	C-Max	01/2012-12/2012	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Ford	Crown Victoria	01/2009-12/2011	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Crown Victoria	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Crown Victoria	01/2008-12/2008	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	E-Series	01/2010-12/2017	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	E-Series	01/2009-12/2010	Band 315MHz		●	●	●	0/S	315Mhz	Lear	●	●
Ford	E-Series	01/2008-12/2008	315MHz		●	●	○	0/S	315Mhz	Lear	●	●
Ford	E-Series	01/2007-12/2007	315MHz		●	●	○	0/S	315Mhz	Lear	●	●
Ford	E-Series	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Ecosport	06/2015-06/2017	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Ford	Ecosport	07/2017-12/2019	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
Ford	Edge	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Edge	01/2007-12/2010	no Chrome rims 315MHz	U387	●	●	●	0/S	315Mhz	Continental	●	●
Ford	Edge	01/2007-12/2007	with Chrome rims 315MHz	U387	●	●	●	0/S	315Mhz	Continental	●	●
Ford	Edge	01/2013-12/2015	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Edge	01/2015-12/2020	315MHz	CD539N	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Edge	01/2011-12/2011	315MHz	U387	●	●	●	S	315Mhz	Schrader	●	●
Ford	Edge	01/2012-12/2012	315MHz	U387	●	●	●	S	315Mhz	Schrader	●	●
Ford	Edge	01/2013-12/2014	315MHz	U387	●	●	●	S	315Mhz	Schrader	●	●
Ford	Escape	01/2013-09/2013	315MHz	C520	●	●	●	S	315Mhz	Schrader	●	●
Ford	Escape	10/2013-12/2014	315MHz	C520	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Escape	01/2012-12/2012	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Escape	01/2008-12/2008	315MHz	U377	●	●	●	0/S	315Mhz	Continental	●	●
Ford	Escape	01/2006-12/2007	315MHz	U204	●	●	○	S	315Mhz	Continental	●	●
Ford	Escape	01/2005-12/2005	315MHz	U204	○	●	○	S	315Mhz	Continental	●	●
Ford	Escape	01/2016-12/2017	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Escape	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Escape	01/2013-12/2013	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Escape	01/2014-12/2016	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Escape	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Escape	01/2017-12/2019	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Escape	01/2009-12/2009	315MHz	U377	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Escape	01/2010-12/2010	315MHz	U377	●	●	○	S	315Mhz	Schrader	●	●
Ford	Escape	01/2011-12/2011	315MHz	U377	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Escape	01/2012-12/2012	315MHz	U377	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Exp Sport Trac	01/2008-12/2010	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Exp Sport Trac	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Expedition	01/2016-12/2017	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Expedition	01/2015-12/2015	433Mhz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Expedition	01/2013-12/2014	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Expedition	01/2007-12/2010	with Chrome rims 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Ford	Expedition	01/2007-12/2010	no Chrome rims 315MHz		●	●	●	0/S	315Mhz	Continental	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	Expedition	01/2005-12/2006	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Expedition	01/2004-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Ford	Expedition	01/2003-12/2003	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Ford	Expedition	01/2016-12/2016	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Expedition	01/2015-12/2015	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Expedition	01/2011-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Expedition	01/2018-12/2020	315MHz		●	●	●	0/S	315MHZ	Schrader	●	●
Ford	Expedition	01/2017-12/2017	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Explorer	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Explorer	10/2015-12/2017	315MHz	U502	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Explorer	06/2015-12/2019	433MHz		●	●	○	0/S	433Mhz	Schrader	●	●
Ford	Explorer	01/2013-05/2015	433Mhz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Explorer	01/2011-12/2012	433Mhz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Explorer	01/2008-12/2010	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Explorer	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Explorer	01/2005-12/2005	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Ford	Explorer	01/2004-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Ford	Explorer	01/2003-12/2003	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Ford	Explorer	01/2002-12/2002	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Ford	Explorer	01/2013-09/2015	315MHz	U502	●	●	●	S	315Mhz	Schrader	●	●
Ford	Explorer	01/2011-12/2011	315MHz	U502	●	●	●	S	315Mhz	Schrader	●	●
Ford	Explorer	01/2012-12/2012	315MHz	U502	●	●	●	S	315Mhz	Schrader	●	●
Ford	F-150	01/2009-12/2010	315MHz	P415	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-150	01/2018-12/2019	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-150	01/2015-12/2018	433MHz	P415	●	●	●	0/S	433Mhz	Schrader	●	●
Ford	F-150	01/2015-12/2017	315MHz	P552	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-150	01/2013-12/2014	433MHz	P415	●	●	●	S	433Mhz	Schrader	●	●
Ford	F-150	01/2006-12/2008	315MHz	P221	●	●	○	S	315Mhz	Continental	●	●
Ford	F-150	01/2012-12/2014	315MHz	P415	●	●	●	S	315Mhz	Schrader	●	●
Ford	F-150	01/2011-12/2011	315MHz	P415	●	●	●	S	315Mhz	Schrader	●	●
Ford	F-150 HD	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-150 HD	01/2008-12/2010	315MHz		●	●	●	0/S	315Mhz	Lear	●	●
Ford	F-150 HD	01/2011-12/2014	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	F-Series	01/2017-12/2019	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-Series	01/2015-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-Series	01/2009-12/2014	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	F-Series	01/2006-12/2008	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	F-Series SD	01/2018-12/2019	315MHz		●	●	●	0/S	315MHZ	Schrader	●	●
Ford	F-Series SD	01/2017-12/2019	Trailer 433MHz		○	●	○	C	433Mhz	Schrader	●	●
Ford	F-Series SD	01/2017-12/2017	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-Series SD	01/2015-12/2018	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	F-Series SD	06/2010-12/2010	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	F-Series SD	01/2009-05/2010	Banded 315MHz		●	●	●	0/S	315Mhz	Lear	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	F-Series SD	01/2007-12/2008	Banded 315MHz		●	●	○	S	315Mhz	Lear	●	●
Ford	F-Series SD	01/2011-12/2016	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	F-Series SD DRW	01/2018-12/2019	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	F-Series SD DRW	01/2018-12/2019	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Ford	F-Series SD DRW	01/2016-12/2017	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Fiesta	01/2018-12/2019	315MHz		●	●	○	S	315MHz	Schrader	●	●
Ford	Fiesta	01/2011-12/2013	315MHz	B299N	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Fiesta	01/2014-12/2017	315MHz	B299N	●	●	○	S	315Mhz	Schrader	●	●
Ford	Fiesta ST	01/2018-12/2019	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Five Hundred	01/2006-12/2007	315MHz	D258	○	●	○	S	315Mhz	Continental	●	●
Ford	Flex	01/2016-12/2019	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Flex	01/2016-12/2019	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Flex	01/2013-12/2015	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Ford	Flex	01/2009-12/2010	315MHz	D471	●	●	●	0/S	315Mhz	Continental	●	●
Ford	Flex	01/2013-12/2019	315MHz	D471	●	●	●	S	315Mhz	Schrader	●	●
Ford	Flex	01/2012-12/2012	315MHz	D471	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Flex	01/2011-12/2011	315MHz	D471	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Focus	01/2014-12/2014	315MHz	C346N	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Focus	01/2013-12/2013	315MHz	C346N	●	●	●	S	315Mhz	Schrader	●	●
Ford	Focus	01/2012-12/2012	315MHz	C170	●	●	●	S	315Mhz	Schrader	●	●
Ford	Focus	01/2010-12/2011	315MHz	C170	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Focus	01/2015-12/2019	315MHz	C346N	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Focus	01/2008-12/2009	315MHz	C170	●	●	●	0/S	315Mhz	Continental	●	●
Ford	Focus	01/2007-12/2007	315MHz	C170	○	●	○	S	315Mhz	Continental	●	●
Ford	Focus RS	01/2016-12/2017	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Focus RS	01/2018-12/2018	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	Focus ST	01/2018-12/2018	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Freestar	01/2006-12/2007	315MHz	V229	●	●	○	S	315Mhz	Continental	●	●
Ford	Freestar	01/2005-12/2005	315MHz	V229	●	●	○	S	315Mhz	Schrader	●	●
Ford	Freestar	01/2004-12/2004	315MHz	V229	○	●	○	S	315Mhz	Schrader	●	●
Ford	Freestyle	01/2005-12/2007	315MHz		○	●	○	S	315Mhz	Continental	●	●
Ford	Fusion	07/2013-12/2016	315MHz	CD391	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Fusion	07/2012-06/2013	315MHz	CD391	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Fusion	01/2018-12/2019	315MHz		●	●	●	0/S	315MHZ	Schrader	●	●
Ford	Fusion	01/2017-12/2020	315MHz	CD539N	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Fusion	01/2017-12/2019	433MHz	CD389	●	●	○	0/S	433Mhz	Schrader	●	●
Ford	Fusion	01/2013-12/2015	433MHz	CD391	●	●	○	0/S	433Mhz	Schrader	●	●
Ford	Fusion	01/2010-06/2012	315MHz	CD338	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Fusion	01/2008-12/2009	315MHz	CD338	●	●	○	S	315Mhz	Continental	●	●
Ford	Fusion	01/2007-12/2007	315MHz	CD338	●	●	○	S	315Mhz	Continental	●	●
Ford	GT	12/2017-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Grand Marquis	01/2007-12/2011	315MHz		○	●	○	S	315Mhz	Continental	●	●
Ford	Interceptor Crown Vic	01/2006-12/2014	315MHz		○	●	○	S	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	Interceptor Explorer	01/2015-08/2015	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Interceptor Explorer	01/2011-12/2014	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Interceptor Explorer	09/2015-12/2019	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Interceptor Taurus	01/2011-12/2019	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Ford	Kuga	01/2014-12/2019	433MHz	C520	●	●	●	0/S/A	433Mhz	Schrader	●	●
Ford	Mustang	01/2005-06/2006	315MHz		○	●	○	S	315Mhz	Continental	●	●
Ford	Mustang	01/2015-12/2018	433MHz	S550	●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Mustang	07/2006-12/2009	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Mustang	01/2013-12/2014	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Mustang	10/2014-12/2017	315MHz	S550	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Mustang	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Mustang	01/2010-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Mustang	01/2012-09/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Ranger	01/2006-12/2007	315MHz	J97	●	●	○	S	315Mhz	Continental	●	●
Ford	Ranger	01/2008-12/2011	315MHz		●	●	○	S	315Mhz	Continental	●	●
Ford	Ranger	01/2012-12/2017	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Ford	Ranger	01/2018-12/2018	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Ranger	01/2019-12/2020	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Shelby GT500	01/2013-12/2015	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Ford	Shelby GT500	01/2012-12/2014	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Ford	Shelby GT500	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Shelby GT500	01/2015-12/2017	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Taurus	01/2017-12/2017	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Taurus	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Taurus	11/2012-12/2015	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Ford	Taurus	01/2012-10/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Taurus	01/2011-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Taurus	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Taurus	11/2015-12/2019	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Taurus	01/2013-10/2015	433MHz		●	●	●	S	433MHz	Schrader	●	●
Ford	Taurus	05/2010-12/2010	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Taurus	01/2008-04/2010	Banded 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Ford	Taurus X	01/2008-12/2009	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Ford	Transit	01/2015-12/2015	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Transit	01/2010-12/2014	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Ford	Transit	01/2017-12/2019	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Transit	01/2014-12/2014	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Ford	Transit	01/2016-12/2016	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Transit Connect	01/2018-12/2018	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Transit Connect	01/2014-12/2017	315MHz	V408N	●	●	●	0/S	315Mhz	Schrader	●	●
Ford	Transit Connect	01/2013-12/2013	315MHz	V408N	●	●	○	0/S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	Transit Connect	01/2012-12/2012	315MHz	V227N	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Transit Connect	01/2019-12/2020	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Transit Connect	01/2010-12/2011	315MHz	V227N	●	●	○	0/S	315Mhz	Schrader	●	●
Ford	Transit LCV	01/2014-12/2019	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Ford	Windstar	01/2001-12/2003	Indirect		○	○	○	S	N/A	N/A	Indirect	●
GMC	Acadia	11/2016-08/2018	315Mhz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Acadia	11/2016-08/2018	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Acadia	01/2014-10/2016	315MHz 25920615		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Acadia	06/2014-10/2016	315MHz 23445327		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Acadia	01/2016-10/2016	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Acadia	09/2018-12/2019	315Mhz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Acadia	01/2013-12/2013	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Acadia	01/2014-12/2015	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Acadia	01/2012-12/2013	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Acadia	11/2008-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Acadia	01/2007-10/2008	315MHz		○	●	○	S	315Mhz	Continental	●	●
GMC	Acadia	09/2018-06/2020	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Canyon	01/2010-12/2012	315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Canyon	01/2007-12/2009	315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Canyon	01/2014-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Canyon	01/2017-06/2020	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Envoy	01/2007-12/2009	SCH Clamp in 315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Envoy	01/2007-12/2007	TRW Clamp in 315MHz		●	●	●	S	315Mhz	TRW	●	●
GMC	Envoy	01/2006-12/2006	315MHz		○	●	○	S	315Mhz	Schrader	●	●
GMC	Envoy	01/2005-12/2005	315MHz		○	●	○	S	315Mhz	Schrader	●	●
GMC	Envoy	01/2007-12/2009	SCH Snap in 315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Savana	01/2014-12/2015	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Savana	01/2009-12/2013	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Savana	01/2009-12/2013	Clamp in 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
GMC	Savana	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
GMC	Savana	01/2017-06/2020	433MHz		○	●	○	S	433Mhz	Schrader	●	●
GMC	Savana	01/2019-06/2020	315MHz		○	●	○	S	315MHz	Schrader	●	●
GMC	Savana	01/2017-12/2018	315Mhz		○	●	○	S	315Mhz	Schrader	●	●
GMC	Savana	01/2016-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Savana	01/2016-12/2016	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Savana	01/2014-12/2015	Clamp in 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
GMC	Sierra	01/2004-12/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Sierra	01/2007-12/2007	TRW Clamp in 315MHz		●	●	●	0/S	315Mhz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
GMC	Sierra	01/2005-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Sierra	01/2007-12/2007	SCH Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Sierra	01/2007-12/2008	SCH Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Sierra	01/2009-12/2013	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Sierra	01/2010-12/2011	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Sierra	01/2014-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Sierra	01/2015-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Sierra	01/2016-12/2018	433Mhz 13598773	XL8	●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Sierra	01/2017-12/2019	315MHz	XL7	●	●	●	0/S	315MHz	Schrader	●	●
GMC	Sierra	01/2018-06/2020	433Mhz 13516165		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Sierra Classic	01/2007-12/2007	315MHz		○	●	○	S	315Mhz	Schrader	●	●
GMC	Sierra DRW	01/2017-12/2019	315MHz	XL7	○	●	○	S	315Mhz	Schrader	●	●
GMC	Sierra DRW	01/2017-12/2019	433Mhz	XL8	○	●	○	S	433Mhz	Schrader	●	●
GMC	Sierra DRW	01/2015-12/2016	315MHz		○	●	○	S	315Mhz	Schrader	●	●
GMC	Terrain	01/2018-06/2020	433MHz		○	●	○	S	433Mhz	Schrader	●	●
GMC	Terrain	01/2018-06/2020	315MHz		○	●	○	S	315MHz	Schrader	●	●
GMC	Terrain	01/2017-12/2017	315MHz		○	●	○	S	315Mhz	Schrader	●	●
GMC	Terrain	01/2012-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Terrain	01/2017-12/2017	433MHz		○	●	○	S	433Mhz	Schrader	●	●
GMC	Terrain	01/2015-12/2016	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Terrain	01/2015-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Terrain	01/2013-12/2014	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Terrain	01/2010-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Yukon A11	03/2014-12/2016	315MHz 13598772		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2016-12/2018	433MHz 13598773		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Yukon A11	01/2017-06/2020	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
GMC	Yukon A11	01/2018-12/2018	433Mhz 13516165		●	●	●	0/S	433Mhz	Schrader	●	●
GMC	Yukon A11	01/2014-12/2014	315MHz 25920615		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2009-12/2013	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2010-12/2011	Clamp in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2007-12/2007	Clamp in 315MHz		●	●	●	0/S	315Mhz	TRW	●	●
GMC	Yukon A11	08/2004-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2004-07/2004	315MHz		●	●	●	S	315Mhz	Schrader	●	●
GMC	Yukon A11	01/2007-12/2007	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Honda	Accord	01/2008-12/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Honda	Accord	01/2013-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	CR-V	01/2012-12/2014	315MHz		●	●	○	0	315Mhz	Continental	●	●
Honda	CR-V	01/2007-12/2011	Alloy/Steel 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Honda	CR-V	01/2014-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	CR-Z	01/2016-12/2016	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	CR-Z	01/2011-12/2017	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Civic	01/2012-12/2014	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Civic	01/2008-12/2011	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Civic	01/2014-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Clarity	01/2016-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Crosstour	01/2010-12/2015	315MHz		●	●	○	0	315Mhz	Continental	●	●
Honda	Element	01/2006-12/2007	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Element	01/2008-12/2008	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Element	01/2009-12/2011	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Fit	01/2008-12/2008	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Honda	Fit	01/2009-12/2014	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Fit	01/2015-12/2017	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Fit	01/2018-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	GL1800	01/2009-12/2015	MOTOR Cycle 315MHz		○	○	○	S	315MHz	Continental	Activate Only	●
Honda	Goldwing	01/2009-12/2016	MOTOR Cycle 315MHz		○	○	○	S	315MHz	Continental	Activate Only	●
Honda	HR-V	09/2014-12/2020	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	HR-V CROSSOVER	01/2016-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Insight	05/2009-12/2014	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Insight	01/2018-12/2020	Indirect		○	○	○	S		N/A	Indirect	●
Honda	Legend Hybrid	01/2015-12/2017	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	NSX	01/2016-12/2019	Direct 433MHz		●	●	○	0	433MHz	Continental	●	●
Honda	Odyssey	01/2011-12/2020	315MHz	EX/EX-L	●	●	○	0	315Mhz	TRW	●	●
Honda	Odyssey	01/2006-12/2007	315MHz	EX/EX-L	●	●	○	0	315Mhz	TRW	●	●
Honda	Odyssey	01/2008-12/2010	315MHz	EX/EX-L	●	●	○	0	315Mhz	TRW	●	●
Honda	Odyssey	01/2018-12/2019	433MHz		●	●	○	0	433MHz	Continental	●	●
Honda	Odyssey Touring	01/2018-12/2019	433MHz		●	●	○	0	433MHz	Continental	●	●
Honda	Odyssey Touring	01/2011-12/2019	315MHz	TOUR	●	●	○	0	315Mhz	TRW	●	●
Honda	Odyssey Touring	01/2008-12/2010	315MHz	TOUR	●	●	○	0	315Mhz	TRW	●	●
Honda	Odyssey Touring	01/2005-12/2007	315MHz	TOUR	●	●	○	0	315Mhz	TRW	●	●
Honda	Pilot	01/2005-12/2005	Steel 315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Pilot	01/2016-12/2017	433MHz		●	●	○	0	433Mhz	Continental	●	●
Honda	Pilot	01/2018-12/2020	433MHz		●	●	○	0	433MHz	Continental	●	●
Honda	Pilot	01/2009-12/2015	Alloy 315MHz		●	●	○	0/A	315Mhz	Pacific	●	●
Honda	Pilot	01/2009-12/2015	Steel 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Honda	Pilot	01/2006-12/2008	315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Pilot	01/2005-12/2005	Alloy 315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Ridgeline	01/2006-12/2008	Alloy 315MHz		●	●	○	0	315Mhz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Honda	Ridgeline	01/2017-12/2019	Alloy 315MHz		●	●	○	0	315MHz	TRW	●	●
Honda	Ridgeline	01/2016-12/2019	Steel 315MHz		●	●	○	0	315MHz	TRW	●	●
Honda	Ridgeline	01/2009-12/2014	Steel 315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Ridgeline	01/2009-12/2014	Alloy 315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Ridgeline	01/2006-12/2008	Steel 315MHz		●	●	○	0	315Mhz	TRW	●	●
Honda	Ridgeline	01/2017-12/2020	433MHz		●	●	○	0	433MHz	Continental	●	●
Honda	S2000	01/2008-12/2009	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Hummer	H2	01/2008-12/2008	315MHz 15922396		●	●	●	0/S	315Mhz	Schrader	●	●
Hummer	H2	01/2008-12/2008	315MHz 13598771		●	●	●	0/S	315Mhz	Schrader	●	●
Hummer	H2	01/2007-12/2007	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Hummer	H2	01/2009-12/2010	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Hummer	H3	01/2007-12/2010	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Hummer	H3	01/2006-12/2006	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Hummer	H3T	01/2006-12/2010	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Hyundai	Accent	04/2011-09/2014	315MHz 529333N000	RB	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Accent	04/2011-06/2020	Hi Line 433MHz	RB	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Accent	01/2006-03/2011	315MHz 529332F000	MC	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Accent	10/2014-06/2020	Lo Line 433MHz	RB	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Accent	04/2011-09/2014	315MHz 529332M000	RB	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Accent	01/2006-12/2007	315MHz	MC	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Accent	04/2011-09/2014	433MHz	RB	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Azera	11/2006-12/2011	315MHz	TG	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Azera	01/2012-12/2014	315MHz	HG	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Azera	01/2012-12/2019	433MHz	HG	●	●	○	0	433Mhz	TRW	●	●
Hyundai	Centennial	01/2013-12/2015	315MHz		●	●	○	0	315Mhz	Continental	●	●
Hyundai	Elantra	01/2015-06/2020	AD 433Mhz	AD	●	●	○	0	433MHz	Continental	●	●
Hyundai	Elantra	10/2013-12/2019	Lo Line 315MHz		●	●	○	0/A	315MHz	TRW	●	●
Hyundai	Elantra	01/2007-12/2010	315MHz	HD	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Elantra	10/2010-12/2013	315MHz	UD/MD	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Elantra GT	01/2013-12/2015	315MHz	GD	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Elantra GT	01/2015-12/2015	433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Elantra GT	01/2016-06/2017	315MHz		●	●	○	0	315Mhz	Continental	●	●
Hyundai	Elantra GT	06/2017-12/2019	PD 433MHz	PD	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Elantra GT	07/2017-12/2019	315MHz		●	●	○	0	315Mhz	Continental	●	●
Hyundai	Elantra Touring	01/2009-12/2012	315MHz	FD	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Entourage	10/2006-06/2008	315MHz	EP	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Entourage	07/2008-12/2010	315MHz	EP	●	●	○	0	315Mhz	Huf/Beru	●	●
Hyundai	Equus	03/2013-06/2016	Hi Line 315MHz	VI	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Equus	01/2010-07/2013	315MHz	VI	●	●	○	0	315Mhz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Hyundai	Genesis	01/2014-12/2017	DH 433Mhz	DH	●	●	○	O/A	433Mhz	Continental	●	●
Hyundai	Genesis	01/2008-12/2014	TRW 315MHz	BH	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Genesis	04/2008-12/2012	BK 315MHz	BK	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Genesis	01/2013-12/2016	BK 315MHz	BK	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Genesis Coupe	01/2008-12/2012	Lo Line 315MHz	BK	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Genesis Coupe	01/2011-12/2016	Hi Line 315MHz	BK	●	●	○	0	315MHz	Continental	●	●
Hyundai	Genesis G70	10/2017-06/2020	433Mhz	IK	●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Genesis G80	07/2016-06/2020	433Mhz	DH	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Genesis G90	07/2016-06/2020	433MHz	HI	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Genesis Sedan	01/2015-06/2016	433MHz	DH	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Genesis Sedan	01/2009-12/2014	315MHz	BH	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Ioniq	01/2016-06/2020	433MHz	AE	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Kona	01/2017-06/2020	433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Nexo	04/2018-06/2020	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Hyundai	Palisade	01/2019-06/2020	433MHz		○	●	○	C	433Mhz	Schrader	●	●
Hyundai	Santa Fe	03/2018-06/2020	TM 433MHZ	TM/TMA	●	●	○	O/A	433Mhz	Schrader	●	●
Hyundai	Santa Fe	01/2008-12/2010	Lo Line 315MHz	CM	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Santa Fe	01/2008-12/2008	315MHz	CM	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Santa Fe	01/2008-12/2008	Hi Line 315MHz	CM	●	●	○	0	315Mhz	Huf/Beru	●	●
Hyundai	Santa Fe	01/2006-12/2007	315MHz	CM	●	●	○	0	315Mhz	Huf/Beru	●	●
Hyundai	Santa Fe	01/2017-06/2020	433MHz	NC	●	●	○	0	433MHz	Continental	●	●
Hyundai	Santa Fe	10/2009-12/2012	315MHz	CM	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Santa Fe	06/2012-12/2014	315MHz	NC	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Santa Fe	01/2014-04/2017	Hi Line 433MHz		●	●	○	0	433Mhz	Continental	●	●
Hyundai	Santa Fe	01/2015-12/2019	315MHz	NC	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Santa Fe Sport	01/2013-12/2014	315Mhz	DMA	●	●	○	0	315MHz	Continental	●	●
Hyundai	Santa Fe Sport	01/2015-12/2019	315MHz	DMA	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Santa Fe Sport	01/2018-12/2019	VDO 433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Santa Fe Sport	01/2018-12/2019	SCH 433MHz		●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Sonata	04/2014-12/2019	Hi Line 433MHz	LF/LFA	●	●	○	0	433MHz	Schrader	●	●
Hyundai	Sonata	04/2017-12/2019	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Sonata	01/2020-12/2020	433Mhz		○	●	○	C	433Mhz	Continental	●	●
Hyundai	Sonata	12/2007-01/2010	315MHz 529332F000	NF	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Sonata	12/2009-05/2014	315MHz 529332M000	YF	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Sonata	01/2006-12/2008	315MHz 529333E000	NF	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Sonata	05/2013-05/2014	Hi Line 315MHz	YF	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Sonata Hybrid	01/2010-12/2019	315MHz	YF HEV	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Sonata Hybrid	01/2011-12/2015	Lo Line 315MHz		●	●	○	0	315Mhz	Continental	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Hyundai	Sonata Hybrid	03/2015-12/2019	Hi Line 433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Tiburon	01/2007-12/2007	Lo Line 315MHz	GK	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tiburon	01/2008-12/2008	Lo Line 315MHz	GK	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tucson	01/2008-12/2009	315Mhz	JM	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tucson	01/2004-12/2007	315Mhz	JM	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tucson	04/2014-12/2017	FUEL CELL 315MHz	LM FCEV	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tucson	08/2013-08/2014	315MHz	LM	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tucson	05/2015-06/2020	Hi Line 433MHz	TL	●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Tucson	09/2014-12/2015	315MHz	LM	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Tucson	01/2010-07/2013	315Mhz	LM	●	●	○	0	315Mhz	TRW	●	●
Hyundai	Veloster	01/2018-06/2020	JS 433Mhz	JS	●	●	○	0	433MHz	Continental	●	●
Hyundai	Veloster	01/2019-06/2020	FS 433MHz	FS	●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Veloster	01/2011-12/2019	FS 315MHz	FS	●	●	○	0/A	315Mhz	Schrader	●	●
Hyundai	Veracruz	01/2006-12/2008	Hi Line 315MHz	EN	●	●	○	0	315Mhz	Huf/Beru	●	●
Hyundai	Veracruz	01/2008-12/2012	Lo Line 315MHz	EN	●	●	○	0	315Mhz	Lear	●	●
Hyundai	Veracruz	01/2013-12/2013	Lo Line 315MHz	EN	●	●	○	0	315Mhz	TRW	●	●
Hyundai	i30	04/2012-12/2014	315MHz		●	●	○	0	315Mhz	Continental	●	●
Infiniti	EX Series	04/2010-09/2018	315MHz	J50	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	EX Series	11/2007-03/2010	315MHz	J50	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	EX Series	01/2008-12/2008	315MHz 40700CD001	J50	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	FX Series	07/2007-08/2010	315MHz	S51	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	FX Series	09/2010-09/2019	315MHz	S51	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	FX Series	11/2002-06/2007	315MHz	S50	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	G Series	01/2007-12/2007	Sedan 315MHz	V36	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	G Series	01/2007-03/2010	315MHz	V36	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	G Series	04/2010-12/2015	315MHz	V36	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	G Series	01/2003-12/2006	315MHz	V35	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	G Series	01/2007-12/2007	Coupe 315MHz	V36	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	JX35	01/2013-12/2014	433MHz	L50	●	●	○	0	433Mhz	Continental	●	●
Infiniti	M Series	01/2011-12/2013	315MHz	Y51	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	M Series	07/2002-12/2008	315MHz	Y34	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	M Series	01/2009-12/2010	315MHz	Y50	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	Q25	01/2011-12/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Infiniti	Q30	01/2015-12/2019	433MHz	GD1A/H15	●	●	○	0/A	433Mhz	Schrader	●	●
Infiniti	Q40	01/2015-06/2018	315MHz	V36	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	Q45	08/2002-08/2006	315MHz	F50	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	Q45	09/2006-12/2007	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Infiniti	Q50	01/2016-12/2019	433MHz	V37	●	●	○	0	433MHz	Continental	●	●
Infiniti	Q50	01/2013-12/2015	315MHz	V37	●	●	○	0	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Infiniti	Q60	05/2016-12/2019	433MHZ	CV37	●	●	○	0	433MHz	Continental	●	●
Infiniti	Q60	01/2014-12/2016	315MHz	CV36/HV36	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	Q70	01/2014-12/2019	315MHz	Y51	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	Q80	01/2017-12/2019	433MHz		●	●	○	0	433MHz	Pacific	●	●
Infiniti	QX30	09/2015-12/2019	433MHz	GD1A/H15	●	●	○	0/A	433Mhz	Schrader	●	●
Infiniti	QX4	01/2003-12/2003	315MHz	JR50	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	QX40	01/2003-12/2003	315MHz	JR50	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	QX50	01/2013-12/2018	315MHz	J50	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	QX50	11/2017-12/2019	433MHz		●	●	○	0	433Mhz	Continental	●	●
Infiniti	QX56	06/2010-12/2013	315MHz	Z62	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	QX56	01/2004-04/2007	315MHz	JA60	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	QX56	05/2007-05/2010	315MHz	JA60	●	●	○	0	315Mhz	Schrader	●	●
Infiniti	QX60	02/2012-12/2019	433MHz	L50	●	●	○	0	433Mhz	Continental	●	●
Infiniti	QX70	01/2014-06/2019	315MHz	S51	●	●	○	0	315Mhz	Pacific	●	●
Infiniti	QX80	01/2017-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Infiniti	QX80	08/2016-12/2017	433MHz	Z62	●	●	○	0	433MHz	Pacific	●	●
Infiniti	QX80	01/2014-12/2016	315MHz	Z62	●	●	○	0	315Mhz	Pacific	●	●
Isuzu	Ascender	01/2006-12/2011	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Isuzu	Rodeo	01/2004-12/2004	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Isuzu	i-290	01/2007-12/2009	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Isuzu	i-370	01/2007-12/2011	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Jaguar	E-Pace	06/2017-12/2019	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	F-Pace	01/2015-12/2019	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	F-Type	01/2014-12/2015	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	F-Type	01/2014-12/2017	315MHz		○	●	○	A	315Mhz	Continental	●	●
Jaguar	F-Type	01/2016-12/2016	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	F-Type	01/2017-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	I-Pace	01/2017-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	S-Type	01/2005-12/2007	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Jaguar	S-Type	01/2005-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	S-Type	01/2008-12/2011	315MHz		○	●	○	A	315Mhz	Continental	●	●
Jaguar	Super V8	01/2005-12/2006	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	Super V8	01/2007-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	Super V8	01/2005-12/2009	315MHz		○	●	○	A	315Mhz	Continental	●	●
Jaguar	Vanden Plas	01/2004-12/2006	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	Vanden Plas	01/2004-12/2009	315MHz		○	●	○	A	315Mhz	Continental	●	●
Jaguar	Vanden Plas	01/2007-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	X-Type	01/2007-12/2011	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Jaguar	X-Type	01/2007-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XE	01/2014-12/2016	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XE	01/2017-12/2019	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XF	10/2016-12/2019	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XF	01/2008-12/2008	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XF	01/2009-12/2015	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XF	01/2016-09/2016	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Jaguar	XF	01/2009-12/2016	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Jaguar	XFR	01/2010-12/2012	315MHz		○	●	○	A	315Mhz	Continental	●	●
Jaguar	XJ	01/2012-12/2016	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Jaguar	XJ	01/2016-12/2019	433Mhz	X351	●	●	○	O/A	433Mhz	Continental	●	●
Jaguar	XJ	01/2006-12/2011	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Jaguar	XJ	01/2006-12/2011	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jaguar	XJ	01/2012-12/2015	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jaguar	XK	01/2010-12/2015	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Jaguar	XK	01/2006-12/2009	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jaguar	XK	01/2005-12/2009	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Jaguar	XK	01/2010-12/2015	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jaguar	XK-S	01/2013-12/2014	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Jaguar	XK-S	01/2015-12/2015	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jeep	Cherokee	12/2015-12/2018	433MHz	KL	●	●	●	O/A	433Mhz	TRW	●	●
Jeep	Cherokee	01/2019-06/2020	433MHz	KL	●	●	●	O/A	433Mhz	TRW	●	●
Jeep	Cherokee	01/2018-12/2019	433MHz 68324960AA		○	●	○	C	433Mhz	TRW	●	●
Jeep	Cherokee	10/2013-11/2015	433MHz	KL	●	●	●	O/A	433Mhz	TRW	●	●
Jeep	Commander	01/2008-12/2011	433MHz	XK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Commander	01/2006-12/2007	315MHz	XK	●	●	●	O/A	315Mhz	Schrader	●	●
Jeep	Compass	01/2017-06/2020	433MHz	MP/MX	●	●	●	O/A	433Mhz	Continental	●	●
Jeep	Compass	01/2007-12/2007	315MHz	MK49	●	●	●	O/A	315Mhz	Continental	●	●
Jeep	Compass	01/2008-12/2009	315MHz	MK49	●	●	●	O/A	315Mhz	Continental	●	●
Jeep	Compass	01/2010-12/2011	315MHz	MK49	●	●	●	O/A	315Mhz	Continental	●	●
Jeep	Compass	01/2012-12/2012	SCH 433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Compass	05/2006-12/2014	VDO 433MHz		●	●	●	O/A	433Mhz	Continental	●	●
Jeep	Compass	01/2019-12/2019	315MHz		●	●	●	O	315Mhz	Schrader	●	●
Jeep	Compass	01/2017-12/2018	315MHz		●	●	●	O	315Mhz	Schrader	●	●
Jeep	Compass	01/2015-12/2015	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Compass	01/2012-12/2016	315MHz	MK49	●	●	●	O/A	315Mhz	Schrader	●	●
Jeep	Gladiator	01/2020-06/2020	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	07/2010-12/2010	433MHz	WK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	01/2008-06/2010	433MHz	WK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	01/2006-12/2007	315MHz	WK	●	●	●	O/A	315Mhz	Schrader	●	●
Jeep	Grand Cherokee	05/2004-12/2005	315MHz	WK	●	●	●	O/A	315Mhz	Continental	●	●
Jeep	Grand Cherokee	01/2001-12/2004	433MHz	WK/WJ	●	●	○	S	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	01/2018-12/2019	433Mhz	WK	●	●	●	O/A	433Mhz	Continental	●	●
Jeep	Grand Cherokee	01/2016-12/2017	433Mhz	WK	●	●	●	O/A	433Mhz	Continental	●	●
Jeep	Grand Cherokee	01/2014-12/2015	433MHz	WK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	01/2012-12/2013	433MHz	WK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	01/2011-12/2011	433MHz	WK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Liberty	01/2005-12/2006	315MHz	KJ	●	●	○	A	315Mhz	Schrader	●	●
Jeep	Liberty	01/2010-12/2012	315MHz	KK	●	●	●	O/A	315Mhz	Schrader	●	●
Jeep	Liberty	01/2009-12/2009	433MHz	KK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Liberty	01/2007-12/2009	315MHz	KJ	●	●	●	O/A	315Mhz	Schrader	●	●
Jeep	Liberty	01/2002-12/2004	433MHz	KJ	●	●	○	A	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Jeep	Patriot	01/2007-12/2016	315MHz	MK	●	●	●	O/A	315Mhz	Continental	●	●
Jeep	Patriot	01/2011-12/2016	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Jeep	Patriot	01/2012-06/2019	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Jeep	Renegade	01/2018-12/2019	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jeep	Renegade	01/2015-12/2016	433Mhz		●	●	●	O/A	433Mhz	Continental	●	●
Jeep	Renegade	01/2017-12/2017	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Jeep	Scrambler	01/2020-12/2020	DT 433Mhz 68293199AA		○	●	○	C	433Mhz	Schrader	●	●
Jeep	Wagoneer	01/2019-06/2020	DT 433Mhz 68293199AA		○	●	○	C	433Mhz	Schrader	●	●
Jeep	Wrangler	01/2010-12/2012	315MHz	JK	●	●	●	O/A	315Mhz	Schrader	●	●
Jeep	Wrangler	01/2018-06/2020	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Wrangler	01/2015-12/2017	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Wrangler	01/2013-12/2014	433MHz	JK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Wrangler	01/2010-12/2012	433MHz		●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Wrangler	06/2008-12/2009	433MHz	JK	●	●	●	O/A	433Mhz	Schrader	●	●
Jeep	Wrangler	01/2007-12/2009	315MHz	JK	●	●	●	O/A	315Mhz	Schrader	●	●
KIA	Amanti	01/2008-12/2008	315MHz	GH	●	●	○	0	315Mhz	TRW	●	●
KIA	Amanti	01/2009-12/2009	315MHz	GH	●	●	○	0	315Mhz	TRW	●	●
KIA	Amanti	01/2007-12/2007	315MHz	GH	●	●	○	0	315Mhz	TRW	●	●
KIA	Borrego	01/2009-12/2011	315MHz	HM	●	●	○	0	315Mhz	TRW	●	●
KIA	Cadenza	01/2014-12/2017	433MHz	VG	●	●	○	0	433MHz	Continental	●	●
KIA	Cadenza	01/2014-12/2017	315MHz	VG	●	●	○	0	315Mhz	Continental	●	●
KIA	Cadenza	01/2017-12/2019	433MHz	YG	●	●	○	0	433MHz	Continental	●	●
KIA	Ceed	05/2018-06/2020	CD 433MHz		●	●	○	O/A	433Mhz	Pacific	●	●
KIA	E-Niro	10/2018-06/2020	433MHz		●	●	○	0	433MHz	Continental	●	●
KIA	Forte	01/2016-12/2018	315MHz		●	●	○	0	315Mhz	TRW	●	●
KIA	Forte	01/2019-06/2020	433MHz		●	●	○	0	433Mhz	Pacific	●	●
KIA	Forte	05/2013-12/2015	315MHz	YD	●	●	○	O/A	315Mhz	TRW	●	●
KIA	Forte	01/2010-04/2013	315MHz	TD	●	●	○	0	315Mhz	Continental	●	●
KIA	K7	01/2016-12/2019	YG 433MHz	YG	●	●	○	0	433MHz	Continental	●	●
KIA	K7	01/2008-12/2012	433MHz	VG	●	●	○	0	433MHz	Continental	●	●
KIA	K7	01/2013-12/2016	VG/Hybrid 433MHz	VG	●	●	○	0	433MHz	Continental	●	●
KIA	K900	01/2019-06/2020	433MHz	RJ	●	●	○	0	433MHz	Schrader	●	●
KIA	K900	01/2015-12/2018	433MHz	KH	●	●	○	0	433MHz	Schrader	●	●
KIA	Magentis	01/2008-12/2010	315MHz		●	●	○	0	315Mhz	Lear	●	●
KIA	Mohave	01/2009-12/2009	Hi Line 315MHz		●	●	○	0	315Mhz	TRW	●	●
KIA	Niro	01/2016-06/2020	433MHz	DE	●	●	○	0	433Mhz	Continental	●	●
KIA	Optima	01/2014-12/2015	315MHz	TF/QF	●	●	○	0	315Mhz	Continental	●	●
KIA	Optima	01/2011-12/2013	315MHz	TF/QF	●	●	○	O/A	315Mhz	Continental	●	●
KIA	Optima	01/2006-12/2010	315MHz	MG	●	●	○	0	315Mhz	Lear	●	●
KIA	Optima	01/2017-06/2020	Hybrid 433MHz	Hybrid	●	●	○	0	433MHz	Continental	●	●
KIA	Optima	01/2016-06/2020	433MHz	JF/JFA	●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
KIA	Optima	01/2016-12/2016	Hybrid 315MHz	Hybrid	●	●	○	0	315MHz	Continental	●	●
KIA	Rio	01/2006-12/2012	315MHz	JB	●	●	○	0	315Mhz	TRW	●	●
KIA	Rio	01/2012-12/2017	315MHz	UB	●	●	○	0	315Mhz	TRW	●	●
KIA	Rio	01/2018-06/2020	433MHz		●	●	○	0	433Mhz	Continental	●	●
KIA	Rondo	01/2013-06/2019	315MHz	RP	●	●	○	0/A	315Mhz	Continental	●	●
KIA	Rondo	01/2006-12/2011	315MHz	UN	●	●	○	0	315Mhz	Lear	●	●
KIA	Sedona	01/2015-06/2020	433MHz	YP	●	●	○	0	433Mhz	Schrader	●	●
KIA	Sedona	01/2006-12/2008	315MHz	VQ	●	●	○	0	315Mhz	Huf/Beru	●	●
KIA	Sedona	01/2009-12/2014	315MHz	VQ	●	●	○	0	315Mhz	Lear	●	●
KIA	Sorento	01/2011-12/2013	315MHz	XM	●	●	○	0	315Mhz	Continental	●	●
KIA	Sorento	01/2016-12/2017	433MHz	UMA	●	●	○	0	433Mhz	Continental	●	●
KIA	Sorento	01/2018-06/2020	433MHz	UMA	●	●	○	0	433MHz	Continental	●	●
KIA	Sorento	01/2014-12/2015	315MHz	XM	●	●	○	0	315Mhz	Continental	●	●
KIA	Sorento	01/2009-12/2010	BL/XM 315MHz	BL/XM	●	●	○	0	315Mhz	TRW	●	●
KIA	Sorento	01/2008-12/2008	BL 315MHz	BL	●	●	○	0	315Mhz	TRW	●	●
KIA	Sorento	01/2005-12/2007	BL 315MHz	BL	●	●	○	0	315Mhz	TRW	●	●
KIA	Soul	01/2019-06/2020	SK3 433MHZ		●	●	○	0	433MHz	Continental	●	●
KIA	Soul	11/2013-12/2019	433MHz	PS	●	●	○	0	433Mhz	Schrader	●	●
KIA	Soul	01/2010-10/2013	315MHz	AM	●	●	○	0	315Mhz	Continental	●	●
KIA	Soul EV	06/2014-12/2019	PS EV 433MHz	PS EV	●	●	○	0	433Mhz	Schrader	●	●
KIA	Spectra	01/2006-12/2009	Lo Line 315MHz	LD	●	●	○	0	315Mhz	TRW	●	●
KIA	Spectra	01/2010-12/2011	Lo Line 315MHz	LD	●	●	○	0	315Mhz	TRW	●	●
KIA	Sportage	01/2005-12/2007	Lo Line 315MHz	KM	●	●	○	0	315Mhz	TRW	●	●
KIA	Sportage	01/2017-06/2020	433MHZ	QL	●	●	○	0	433MHz	Continental	●	●
KIA	Sportage	01/2009-12/2010	Lo Line 315MHz	KM/SL	●	●	○	0	315Mhz	TRW	●	●
KIA	Sportage	01/2008-12/2008	Lo Line 315MHz	KM	●	●	○	0	315Mhz	TRW	●	●
KIA	Sportage	01/2011-12/2013	Lo Line 315MHz	KM/SL	●	●	○	0	315Mhz	TRW	●	●
KIA	Sportage	01/2014-12/2014	315MHz	SL	●	●	○	0	315Mhz	TRW	●	●
KIA	Sportage	01/2015-12/2016	315MHz	SL	●	●	○	0	315Mhz	TRW	●	●
KIA	Stinger	10/2017-06/2020	433Mhz	CK	●	●	○	0	433Mhz	Schrader	●	●
KIA	Telluride	01/2019-06/2020			○	●	○	C	433Mhz	Schrader	●	●
KIA	Tuscany	01/2007-12/2008	315Mhz	YN	○	●	○	C	315Mhz	TRW	●	●
Lamborghini	140 Gallardo Superleggera	01/2012-12/2012	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
Lamborghini	Aventador	01/2012-12/2019	433Mhz	LB834	○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	Gallardo	01/2007-12/2013	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	Huracan	01/2014-06/2020	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	Huracan	01/2015-12/2016	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
Lamborghini	Murcielago	01/2007-12/2011	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	One off	01/2016-06/2020	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	Reventon	01/2008-12/2010	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Lamborghini	Urus	01/2018-06/2020	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Land Rover	Defender	01/2015-12/2015	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Discovery	01/2017-12/2019	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Discovery	01/2017-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Discovery	01/2016-12/2016	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Discovery Sport	09/2015-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Discovery Sport	01/2015-08/2015	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	LR2	01/2010-12/2015	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	LR2	01/2008-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	LR2	01/2008-12/2015	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	LR3	01/2006-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	LR3	01/2010-12/2014	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	LR3	01/2006-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	LR3	01/2002-12/2005	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Land Rover	LR3	01/2010-12/2014	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	LR4	01/2010-12/2016	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	LR4	01/2010-12/2016	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	01/2017-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	01/2014-12/2016	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	03/2002-12/2004	433MHz	L30	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Land Rover	Range Rover	01/2005-12/2006	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	01/2006-12/2006	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover	01/2007-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover	01/2007-12/2013	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	01/2010-12/2013	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover	01/2014-12/2015	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover Evoque	01/2014-12/2017	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Evoque	01/2011-12/2014	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover Evoque	01/2018-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Evoque	01/2015-12/2016	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover Grand Evoque	01/2017-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-12/2013	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover Sport	01/2006-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Land Rover	Range Rover Sport	01/2006-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Sport	01/2014-12/2015	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-12/2013	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Sport	01/2014-12/2017	315MHz		●	●	○	0/A	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Land Rover	Range Rover Sport	01/2016-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Velar	01/2017-06/2020	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Lexus	CT Series	12/2010-08/2017	PMV107J 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	CT Series	06/2013-12/2019	PMVC010 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	ES Series	08/2018-12/2019	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	ES Series	08/2006-06/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	ES Series	07/2012-07/2018	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	GS Series	01/2005-03/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	GS Series	04/2012-12/2019	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	GS Series	01/2012-12/2019	433Mhz	920L	●	●	○	0	433Mhz	Pacific	●	●
Lexus	GX Series	01/2004-03/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	GX Series	04/2012-12/2019	PMVC010 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	GX Series	04/2012-08/2017	PMV107J 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	HS Series	07/2009-12/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	IS Series	04/2013-12/2019	PMV-C010 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	IS Series	01/2006-07/2015	PMV-107J 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	LC Series	01/2017-12/2019	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	LC Series	01/2018-12/2019	315Mhz		●	●	○	0	315MHz	Pacific	●	●
Lexus	LFA	12/2010-12/2013	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	LS Series	09/2012-09/2017	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	LS Series	10/2017-12/2019	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	LS Series	01/2007-08/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	LX Series	01/2013-12/2015	PMVC010 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	LX Series	09/2015-12/2019	315Mhz		●	●	○	0	315MHz	Pacific	●	●
Lexus	LX Series	01/2005-09/2015	PMV107J 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	NX Series	01/2014-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	RC Series	01/2014-12/2019	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	RX Series	10/2015-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Lexus	RX Series	07/2013-9/2015	315MHz Japan		●	●	○	0	315Mhz	Pacific	●	●
Lexus	RX Series	07/2013-09/2015	315MHz USA		●	●	○	0	315Mhz	Pacific	●	●
Lexus	RX Series	01/2006-06/2013	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	SC Series	08/2006-12/2010	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Lexus	UX Series	10/2018-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Lifan	MaiWei	01/2016-12/2018	433MHz		●	●	○	0	433MHz	LiFan	●	●
Lincoln	Aviator	01/2003-12/2003	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Lincoln	Aviator	01/2005-12/2005	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Lincoln	Aviator	01/2004-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Lincoln	Aviator	01/2019-12/2020	315MHz		○	●	○	S	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Lincoln	CUV	01/2014-12/2018	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	Continental	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Lincoln	Continental	01/2017-12/2019	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Lincoln	Continental	01/2017-12/2017	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	MKC	01/2015-12/2015	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKC	01/2016-12/2017	315Mhz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKC	06/2015-12/2018	433MHz	2. OF SEL	●	●	●	0/S	433Mhz	Schrader	●	●
Lincoln	MKC	01/2018-12/2019	315MHz		●	●	●	0/S	315MHZ	Schrader	●	●
Lincoln	MKS	01/2013-12/2016	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	MKS	01/2009-12/2010	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Lincoln	MKS	01/2011-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKS	01/2012-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKS	01/2013-12/2016	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Lincoln	MKS	01/2017-12/2019	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	MKT	01/2013-12/2015	433Mhz		●	●	●	S	433Mhz	Schrader	●	●
Lincoln	MKT	06/2011-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKT	01/2010-12/2010	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Lincoln	MKT	01/2016-12/2019	433Mhz		●	●	●	S	433Mhz	Schrader	●	●
Lincoln	MKT	01/2018-12/2019	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKT	01/2013-12/2015	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	MKT	01/2011-05/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKT	01/2016-12/2017	315Mhz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	MKX	07/2015-12/2019	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
Lincoln	MKX	01/2013-07/2015	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	MKX	01/2012-12/2012	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	MKX	01/2011-12/2011	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	MKX	01/2013-06/2015	433MHz		●	●	●	S	433MHZ	Schrader	●	●
Lincoln	MKX	01/2008-12/2010	no Chrome rims 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Lincoln	MKX	01/2008-12/2010	with Chrome rims 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Lincoln	MKX	01/2007-12/2007	with Chrome rims 315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	MKX	01/2007-12/2007	no Chrome rims 315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	MKX	01/2018-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Lincoln	MKX	08/2015-12/2019	315Mhz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKZ	01/2013-12/2016	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKZ	01/2010-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	MKZ	01/2017-12/2019	315MHz		●	●	●	0/S	315MHZ	Schrader	●	●
Lincoln	MKZ	09/2015-12/2019	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Lincoln	MKZ	01/2013-08/2015	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Lincoln	MKZ	01/2008-12/2009	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	MKZ	01/2007-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Mark LT	01/2013-12/2014	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Lincoln	Mark LT	01/2010-12/2014	315MHz		○	●	○	S	315Mhz	Schrader	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Lincoln	Mark LT	01/2009-12/2009	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	Mark LT	01/2015-12/2016	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	Mark LT	01/2008-12/2008	Lear 315MHz		●	●	○	S	315Mhz	Lear	●	●
Lincoln	Mark LT	01/2007-12/2008	VDO 315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Nautilus	01/2019-12/2020	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	Navigator	01/2016-12/2018	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Lincoln	Navigator	01/2016-12/2017	315Mhz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	Navigator	01/2015-12/2015	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Lincoln	Navigator	01/2012-12/2014	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	Navigator	01/2011-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Lincoln	Navigator	01/2003-12/2003	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Lincoln	Navigator	01/2015-12/2015	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Lincoln	Navigator	01/2013-12/2014	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Lincoln	Navigator	01/2008-12/2010	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Lincoln	Navigator	01/2007-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Navigator	01/2005-12/2006	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Lincoln	Navigator	01/2004-12/2004	433MHz		●	●	○	S	433Mhz	Schrader	●	●
Lincoln	Navigator	01/2018-12/2020	315MHz		●	●	●	0/S	315MHZ	Schrader	●	●
Lincoln	Town Car	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Town Car	01/2012-12/2012	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Lincoln	Town Car	01/2010-12/2011	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Town Car	01/2009-12/2009	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Town Car	01/2008-12/2008	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lincoln	Zephyr	01/2010-12/2012	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Lincoln	Zephyr	01/2006-12/2009	315MHz		●	●	○	S	315Mhz	Continental	●	●
Lotus	3 Eleven	01/2014-12/2019	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Lotus	Elise	01/2008-12/2018	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Lotus	Evora	01/2010-06/2020	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Lotus	Exige	09/2000-12/2020	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Maserati	Coupe	07/2009-12/2013	433MHz	M145	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Maserati	Coupe	04/2004-06/2009	433MHz	M145	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Maserati	Ghibli	01/2013-12/2019	433MHz	M156/ M157	●	●	○	0/A	433Mhz	Schrader	●	●
Maserati	GranCabrio	01/2010-12/2013	433MHz		●	●	○	0	433Mhz	Huf/Beru	●	●
Maserati	GranSport	01/2005-12/2006	433MHz		●	●	○	0	433Mhz	Huf/Beru	●	●
Maserati	GranTurismo	01/2017-12/2019	433MHz	M156/ M157	○	●	○	A	433Mhz	Schrader	●	●
Maserati	GranTurismo	01/2011-12/2016	433MHz		●	●	○	0	433Mhz	Huf/Beru	●	●
Maserati	GranTurismo	01/2008-12/2010	433MHz	M145	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Maserati	GranTurismo	01/2012-12/2015	315MHz	M145 GL	●	●	○	A	315Mhz	Huf/Beru	●	●
Maserati	Levante	01/2015-06/2020	433MHz	M161	●	●	○	0/A	433Mhz	Schrader	●	●
Maserati	Quattroporte	01/2013-06/2020	433MHz	M156	●	●	○	0/A	433Mhz	Schrader	●	●
Maserati	Quattroporte	01/2010-12/2012	315MHz	M139	●	●	○	C	315Mhz	Huf/Beru	●	●
Maserati	Quattroporte	01/2011-12/2013	433MHz	M139	●	●	○	A	433Mhz	Huf/Beru	●	●
Maserati	Quattroporte	01/2004-12/2010	433MHz	M139	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Maserati	Spyder	01/2002-12/2005	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Maybach	Landulet	01/2015-12/2019	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
Maybach	Landulet	01/2009-12/2012	315MHz		●	●	○	O/S	315Mhz	Huf/Beru	●	●
Maybach	Maybach 57	02/2002-12/2013	433Mhz	Ma007	●	●	○	O/S	433Mhz	Huf/Beru	●	●
Maybach	Maybach 57	01/2002-12/2012	315MHz		●	●	○	O/S	315Mhz	Huf/Beru	●	●
Maybach	Maybach 62	02/2002-12/2013	433Mhz	Ma007	●	●	○	O/S	433Mhz	Huf/Beru	●	●
Maybach	Maybach 62	01/2002-12/2012	315MHz		●	●	○	O/S	315Mhz	Huf/Beru	●	●
Maybach	S Series	01/2015-12/2019	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
Mazda	Atenza	01/2016-12/2018	433MHz		○	●	○	A	433Mhz	Continental	●	●
Mazda	BT Pickup	01/2010-12/2011	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Mazda	BT Pickup	01/2006-12/2009	315MHz		○	●	○	S	315Mhz	Continental	●	●
Mazda	CX-3	01/2016-12/2019	315MHz		○	●	○	A	315Mhz	Continental	●	●
Mazda	CX-3	01/2016-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-5	01/2018-12/2019	433MHz	J53C/J72A	○	●	○	A	433Mhz	Continental	●	●
Mazda	CX-5	01/2017-12/2019	Direct 315MHz		○	●	○	A	315Mhz	Continental	●	●
Mazda	CX-5	01/2016-12/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-5	01/2013-12/2015	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-6	01/2014-12/2015	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-7	01/2011-12/2012	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	CX-7	01/2010-12/2010	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	CX-7	01/2007-12/2009	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	CX-9	01/2016-12/2017	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-9	01/2013-12/2019	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	CX-9	01/2007-12/2012	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	MX-5	05/2010-12/2017	Indirect	ND	○	○	○	A	N/A	N/A	Indirect	●
Mazda	MX-5	01/2018-12/2019	315MHz	ND	●	●	○	A	315Mhz	Continental	●	●
Mazda	MX-5	01/2011-12/2014	433MHz	NC/J04C/J12 A	●	●	○	A	433Mhz	Continental	●	●
Mazda	MX-5	03/2010-04/2015	315MHz	NC/J04C/J12 A	●	●	○	A	315Mhz	Continental	●	●
Mazda	MX-5 Miata	01/2006-12/2015	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	MX-5 Miata	06/2018-12/2020	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	MX-5 Miata	01/2016-05/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 2	06/2014-12/2015	315MHz		○	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 2	01/2011-05/2014	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 3	01/2014-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 3	01/2011-12/2013	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 3	01/2010-12/2010	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 3	01/2007-12/2009	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 3	01/2005-12/2006	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 3	01/2004-12/2004	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 5	01/2014-12/2015	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 5	01/2011-12/2015	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 5	01/2008-12/2010	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 5	01/2006-12/2007	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 6	01/2008-12/2008	315MHz		●	●	○	A	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mazda	Mazda 6	01/2005-12/2007	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 6	01/2018-12/2020	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 6	01/2014-12/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 6	01/2011-12/2013	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Mazda 6	01/2009-12/2010	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	RX-8	01/2011-12/2011	315MHz		○	●	○	A	315Mhz	Continental	●	●
Mazda	RX-8	01/2009-12/2010	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	RX-8	01/2005-12/2008	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	RX-8	01/2004-12/2004	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Speed 3	01/2007-12/2012	315MHz		●	●	○	A	315Mhz	Continental	●	●
Mazda	Speed 6	01/2007-12/2008	315MHz		○	●	○	A	315Mhz	Continental	●	●
Mazda	Tribute	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mazda	Tribute	01/2011-12/2011	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Mazda	Tribute	01/2010-12/2010	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Mazda	Tribute	01/2009-12/2009	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Mazda	Tribute	01/2008-12/2008	315MHz		○	●	○	S	315Mhz	Continental	●	●
McLaren	500 Series	01/2015-12/2019	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	500 Series	01/2017-12/2019	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	600 Series	03/2014-12/2019	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	700 Series	01/2017-12/2019	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	MP4-12C	06/2011-04/2014	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	P1	01/2013-12/2019	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	Senna	01/2017-12/2019	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Mercedes	A Class	06/2018-12/2019	433Mhz	W177	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	A Class	04/2014-05/2018	433Mhz	W176	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	AMG	01/2013-06/2018	433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	AMG GT	11/2018-12/2019	X290		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	AMG GT	01/2014-06/2020	C190 433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	B Class	02/2019-06/2020	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	B Class	01/2014-12/2018	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	C Class	01/2007-08/2014	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	C Class	09/2014-05/2018	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	C Class	06/2018-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	CL Class	01/2010-12/2015	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	CL Class	01/2007-12/2010	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	CL Class	01/2007-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	CL Class	01/2000-12/2006	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	CL Class	01/2000-12/2006	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	CLA Class	05/2019-06/2020	433Mhz	C118	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	CLA Class	01/2014-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	CLK Class	01/2006-12/2009	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	CLK Class	01/2006-12/2009	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	CLS Class	01/2006-12/2011	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	CLS Class	01/2018-12/2019	C218 433Mhz	C218	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	CLS Class	01/2012-12/2017	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mercedes	CLS Class	01/2006-12/2011	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	CLS Class	01/2005-12/2005	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	CLS Class	01/2018-06/2020	C257 433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	E Class	01/2017-12/2019	W213/BR238 433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	E Class	06/2010-12/2018	W212 433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	E Class	07/2009-05/2014	433MHz	W212	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	E Class	01/2006-05/2010	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	E Class	01/2006-12/2010	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	E Class	01/2000-12/2005	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	E Class	01/2000-12/2005	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	G Class	06/2018-06/2020	433Mhz	G463/461	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	G Class	01/2007-12/2018	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	G Class	04/2007-05/2018	433MHz	463	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	G Class	01/2018-12/2019	315Mhz	G463/461	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GL Class	04/2006-09/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	GL Class	01/2007-12/2010	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	GL Class	10/2009-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GLA Class	01/2014-12/2017	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GLA Class	01/2018-06/2020	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Mercedes	GLB Class	01/2019-06/2020	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	GLC Class	06/2015-12/2019	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Mercedes	GLE Class	01/2016-12/2019	433Mhz	X166	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GLE Class	01/2019-06/2020	433Mhz	V167	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	GLK Class	01/2010-12/2017	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GLS Class	01/2016-06/2019	433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GLS Class	07/2019-06/2020	433Mhz	X167	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	GLT	06/2017-12/2019	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Mercedes	GT	01/2015-12/2019	433MHz	GT	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GT-S	01/2016-12/2019	433Mhz	X166	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	GT-S AMG	01/2019-12/2019	433MHz (A0009052102)		○	●	○	A	433MHz	Schrader	●	●
Mercedes	GT-S AMG	01/2014-12/2019	433MHz	C190	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	M Class	01/2010-12/2014	433MHz	W166	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	M Class	01/2006-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	M Class	01/2015-12/2015	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	M Class	01/2005-05/2011	433Mhz	W164	●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	ML Class	01/2017-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	ML Class	06/2010-12/2016	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	ML Class	01/2006-12/2010	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	ML Class	01/2006-05/2010	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	Metris	01/2015-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	R Class	01/2010-12/2018	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	R Class	01/2006-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	R Class	01/2006-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mercedes	S Class	01/2018-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	S Class	01/2016-12/2017	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	S Class	01/2010-12/2015	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	S Class	12/2005-12/2013	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	S Class	01/2007-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	S Class	01/2000-11/2005	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	S Class	01/2000-12/2006	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	S Class coupe	01/2013-06/2020	433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	SL Class	05/2005-12/2012	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	SL Class	05/2005-06/2012	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	SL Class	01/2000-04/2005	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	SL Class	01/2000-04/2005	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	SL Class	07/2012-12/2017	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	SL Class	01/2018-12/2019	433MHz	R172	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	SLC Class	01/2016-07/2019	433MHz	R172	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	SLK Class	01/2008-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	SLR Class	01/2000-12/2007	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	SLR Class	01/2008-12/2009	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Mercedes	SLR Class	01/2008-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	SLR Class	01/2001-12/2007	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	SLR McLaren	01/2004-12/2007	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Mercedes	SLR McLaren	01/2008-12/2009	315MHz		●	●	○	0/A	315Mhz	Continental	●	●
Mercedes	SLR McLaren	01/2004-12/2011	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Mercedes	SLS Class	01/2010-12/2015	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	Sprinter	01/2018-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	Sprinter	01/2010-12/2017	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	Sprinter	01/2007-12/2014	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Mercedes	V Class	01/2014-12/2019	433Mhz	W447	●	●	○	0/A	433Mhz	Schrader	●	●
Mercedes	X Class	01/2017-12/2019	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Mercury	Grand Marquis	01/2009-12/2011	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Grand Marquis	01/2008-12/2008	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Grand Marquis	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Mariner	01/2011-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Mercury	Mariner	01/2010-12/2010	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Mercury	Mariner	01/2009-12/2009	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Mercury	Mariner	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Mercury	Mariner	01/2005-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Milan	01/2008-12/2009	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Milan	01/2010-12/2012	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Mercury	Montego	01/2006-12/2007	315MHz		○	●	○	S	315Mhz	Continental	●	●
Mercury	Monterey	01/2004-12/2004	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mercury	Monterey	01/2004-12/2004	315MHz		○	●	○	S	315MHz	Schrader	●	●
Mercury	Monterey	01/2005-12/2005	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mercury	Monterey	01/2005-12/2005	315MHz		●	●	○	S	315Mhz	Schrader	●	●
Mercury	Monterey	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mercury	Mountaineer	01/2008-12/2010	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Mountaineer	01/2006-12/2007	315MHz		●	●	○	S	315Mhz	Continental	●	●
Mercury	Mountaineer	01/2005-12/2005	433MHz		●	●	○	S	433MHz	Schrader	●	●
Mercury	Mountaineer	01/2004-12/2004	433MHz		●	●	○	S	433MHz	Schrader	●	●
Mercury	Mountaineer	01/2002-12/2003	433MHz		●	●	○	S	433MHz	Schrader	●	●
Mercury	Sable	01/2008-12/2009	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Mini	Cabrio	01/2016-12/2019	F57 433MHz	F57	●	●	○	A	433Mhz	Continental	●	●
Mini	Cabrio	07/2014-12/2015	R57 433MHz	R57	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Cabrio	01/2010-06/2014	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Cabrio	01/2004-12/2006	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mini	Cabrio	01/2007-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Clubman	11/2013-12/2019	433Mhz	F54	●	●	○	A	433Mhz	Continental	●	●
Mini	Clubman	10/2006-10/2013	433Mhz (36106856227)		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Clubman	10/2006-07/2010	433MHz (36236798726)		●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Clubvan	01/2016-12/2019	433MHz	F54	●	●	○	A	433Mhz	Continental	●	●
Mini	Convertible	01/2017-12/2019	433MHz	R57	●	●	○	A	433Mhz	Continental	●	●
Mini	Cooper	03/2014-12/2019	433MHz		●	●	○	A	433Mhz	Continental	●	●
Mini	Cooper	01/2010-02/2014	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Cooper	01/2007-12/2009	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Countryman	01/2009-06/2014	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Countryman	07/2015-06/2020	433Mhz	F60	●	●	○	A	433Mhz	Continental	●	●
Mini	Countryman	07/2014-12/2018	433Mhz	R60	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Coupe	12/2010-07/2014	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Coupe	08/2014-12/2016	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Hardtop	01/2010-12/2016	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Hardtop	01/2017-12/2018	433MHz		●	●	○	A	433Mhz	Continental	●	●
Mini	Hardtop	01/2004-12/2006	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mini	Hardtop	01/2007-12/2009	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Hatchback	11/2013-12/2019	433Mhz	F56	●	●	○	A	433Mhz	Continental	●	●
Mini	Mini	03/2014-12/2019	433MHz	F55/F56	●	●	○	A	433Mhz	Continental	●	●
Mini	Mini	01/2007-12/2009	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Paceman	07/2018-12/2019	433Mhz		●	●	○	A	433Mhz	Continental	●	●
Mini	Paceman	07/2014-06/2018	433Mhz	R61	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Paceman	01/2009-06/2014	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Roadster	05/2014-12/2019	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mini	Roadster	01/2012-04/2014	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mitsubishi	Colt Plus	07/2016-06/2019	433MHz		●	●	○	O	433Mhz	Schrader	●	●
Mitsubishi	Eclipse	01/2006-12/2009	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Mitsubishi	Eclipse	01/2010-12/2012	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Mitsubishi	Eclipse	01/2017-12/2019	315MHz		●	●	○	O	315Mhz	Continental	●	●
Mitsubishi	Eclipse Cross	01/2017-12/2019	315MHz		●	●	○	O	315Mhz	Continental	●	●
Mitsubishi	Endeavor	09/2010-12/2012	Alloy 315MHz		●	●	○	O	315Mhz	Schrader	●	●
Mitsubishi	Endeavor	09/2010-12/2012	Steel 315MHz		●	●	○	O	315Mhz	Schrader	●	●
Mitsubishi	Endeavor	01/2004-12/2007	433MHz		●	●	○	O	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mitsubishi	Endeavor	01/2006-08/2010	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	Galant	01/2004-12/2006	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Mitsubishi	Galant	01/2007-12/2010	315Mhz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	Galant	01/2011-12/2013	Steel 315MHz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	Galant	01/2011-12/2013	Alloy 315MHz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	Heavy Duty	01/2008-12/2009	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	Lancer	01/2006-12/2010	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Lancer	01/2011-06/2019	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Mirage	01/2018-12/2020	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Mirage	01/2014-12/2017	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Montero	01/2003-12/2006	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	Outlander	01/2006-12/2010	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Outlander	01/2011-12/2019	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Outlander Sport	01/2010-12/2017	315Mhz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Outlander Sport	01/2018-12/2020	Clamp-in 315Mhz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Outlander Sport	01/2018-12/2020	Snap-in 315MHz		○	●	○	0	315Mhz	Continental	●	●
Mitsubishi	RVR	01/2010-12/2020	315MHz		●	●	○	0	315Mhz	Continental	●	●
Mitsubishi	Raider	01/2008-12/2010	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Mitsubishi	i-MiEV	01/2010-12/2016	315MHz		●	●	○	0	315Mhz	Continental	●	●
Nissan	350Z	01/2007-12/2009	315MHz	Z33	●	●	○	0	315Mhz	Schrader	●	●
Nissan	350Z	06/2002-12/2006	315MHz	Z33	●	●	○	0	315Mhz	Schrader	●	●
Nissan	370Z	01/2018-12/2018	Non iKey 315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	370Z	10/2008-03/2010	315MHz	Z34	●	●	○	0	315Mhz	Pacific	●	●
Nissan	370Z	05/2010-12/2019	315MHz	Z34	●	●	○	0	315Mhz	Pacific	●	●
Nissan	Altima	10/2018-06/2020	433MHz	L33	●	●	○	0	433Mhz	Continental	●	●
Nissan	Altima	01/2006-12/2011	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Nissan	Altima	01/2012-12/2014	315MHz		●	●	○	0	315Mhz	Continental	●	●
Nissan	Altima	05/2012-09/2018	433MHz	L33	●	●	○	0	433Mhz	Continental	●	●
Nissan	Altima Coupe	01/2006-12/2013	Coupe 315MHz		●	●	○	0	315Mhz	Schrader	●	●
Nissan	Altima Sedan	01/2006-12/2012	315MHz	L33	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Armada	08/2003-12/2006	Alloy 315MHz	TA60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Armada	01/2007-12/2008	315MHz	TA60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Armada	01/2009-12/2016	315MHz	TA60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Armada	08/2003-12/2006	Steel 315MHz	TA60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Armada	06/2017-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Armada	01/2017-12/2017	433MHz	Y62	●	●	○	0	433MHz	Pacific	●	●
Nissan	Armada GCC	01/2013-12/2014	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Nissan	Cima	01/2017-06/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cima	01/2012-12/2016	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Nissan	Cube	06/2012-02/2014	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cube	11/2011-11/2013	315MHz	B17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Cube	01/2011-12/2015	Smart key 315MHz	Z12	●	●	○	0	315Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Nissan	Cube	01/2009-12/2015	Standard key 315MHz	Z12	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Frontier	09/2006-12/2008	Steel 315MHz	D40	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Frontier	10/2004-12/2006	315MHz	D40	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Frontier	01/2016-06/2019	315MHz	D40	●	●	○	0	315Mhz	Continental	●	●
Nissan	Frontier	01/2003-07/2004	315MHz	D22	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Frontier	01/2008-12/2008	Alloy 315MHz	D40	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Frontier	01/2009-12/2019	315MHz Schrader	D40	●	●	○	0	315Mhz	Schrader	●	●
Nissan	GT-R	01/2007-12/2019	315MHz	R35	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Juke	01/2010-12/2019	Smart key 315MHz	F15	●	●	○	0	315Mhz	Pacific	●	●
Nissan	Juke	01/2010-12/2017	Standard key 315MHz	F15	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Juke	07/2012-07/2014	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Kicks	10/2017-06/2020	433MHz		●	●	○	0	433Mhz	Pacific	●	●
Nissan	Leaf	12/2017-06/2020	433MHz		●	●	○	0	433Mhz	Continental	●	●
Nissan	Leaf	01/2013-12/2019	315MHz	ZE0	●	●	○	0	315Mhz	Continental	●	●
Nissan	Leaf	10/2010-12/2012	315MHz	ZE0	●	●	○	0	315Mhz	Pacific	●	●
Nissan	Leaf Korea	01/2015-12/2019	433MHz		●	●	○	0	433Mhz	Continental	●	●
Nissan	Maxima	01/2008-12/2011	315MHz	A35	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Maxima	01/2007-12/2007	Alloy 315MHz	A34	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Maxima	01/2007-12/2007	Steel 315MHz	A34	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Maxima	01/2006-12/2006	315MHz	A34	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Maxima	01/2012-12/2014	315MHz	A35	●	●	○	0	315Mhz	Continental	●	●
Nissan	Maxima	01/2015-12/2015	315MHz	A35	●	●	○	0	315Mhz	Continental	●	●
Nissan	Maxima	04/2015-12/2019	433Mhz	A36	●	●	○	0	433Mhz	Continental	●	●
Nissan	Maxima GCC	01/2013-12/2014	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Nissan	Micra	03/2017-06/2020	433MHz	K14	●	●	○	0	433Mhz	Continental	●	●
Nissan	Micra	01/2014-02/2017	433MHz	K13	●	●	○	0	433Mhz	Continental	●	●
Nissan	Murano	08/2006-09/2014	315MHz	Z51	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Murano	10/2014-12/2019	433MHz	Z52	●	●	○	0	433Mhz	Continental	●	●
Nissan	Murano	09/2002-07/2006	315MHz	Z50	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Murano	11/2011-12/2013	315MHz Pacific		●	●	○	0	315Mhz	Pacific	●	●
Nissan	NV1500/2500/3500	01/2011-06/2020	315MHz	F80	●	●	○	0	315Mhz	Schrader	●	●
Nissan	NV200	10/2014-12/2019	315MHz		●	●	○	0	315Mhz	Continental	●	●
Nissan	NV200	11/2012-09/2014	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Nissan	NV200 Taxi	01/2018-06/2020	315MHz		●	●	○	0	315Mhz	Continental	●	●
Nissan	NV200 Taxi	01/2014-12/2017	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Nissan	Pathfinder	11/2015-12/2019	433MHz	R52/P61B	●	●	○	0	433Mhz	Continental	●	●
Nissan	Pathfinder	01/2004-12/2006	315MHz	R51	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Pathfinder	01/2007-12/2012	315MHz	R51	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Pathfinder	01/2013-10/2015	433MHz	R52	●	●	○	0	433Mhz	Continental	●	●
Nissan	Pathfinder	07/2002-12/2003	315MHz	R50	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Patrol	01/2008-08/2016	433MHz	Y61	●	●	○	0	433Mhz	Pacific	●	●
Nissan	Patrol	01/2016-12/2019	433MHz	Y62	●	●	○	0	433Mhz	Pacific	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Nissan	Qashqai	06/2019-12/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Nissan	Qashqai	01/2017-05/2019	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Nissan	Quest	11/2010-12/2019	315MHz	E52	●	●	○	0	315Mhz	Pacific	●	●
Nissan	Quest	01/2005-12/2007	Steel 315MHz	V42	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Quest	05/2003-12/2004	315MHz	V42	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Quest	01/2005-12/2007	Alloy 315MHz	V42	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Quest	01/2008-12/2010	315MHz	V42	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Rogue	10/2015-12/2016	Korean 433MHz		●	●	○	0	433Mhz	Continental	●	●
Nissan	Rogue	01/2008-12/2016	Steel 315MHz	S35	●	●	○	0	315MHz	Pacific	●	●
Nissan	Rogue	01/2008-12/2016	Alloy 315MHz	S35	●	●	○	0	315MHz	Schrader	●	●
Nissan	Rogue	10/2013-12/2019	433MHz	T32	●	●	○	0	433Mhz	Continental	●	●
Nissan	Rogue Select	01/2014-12/2015	433MHz	S35	●	●	○	0	433Mhz	Continental	●	●
Nissan	Rogue Select	01/2014-12/2019	315MHz	S35	●	●	○	0	315Mhz	Pacific	●	●
Nissan	Rogue Sport	01/2017-12/2019	433MHz		●	●	○	0	433Mhz	Continental	●	●
Nissan	Sentra	01/2018-12/2019	Smart key 315MHz	B17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Sentra	01/2017-12/2017	Smart key 315MHz	B17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Sentra	01/2016-07/2016	433MHz 407003AR1A		●	●	○	0	433Mhz	Continental	●	●
Nissan	Sentra	11/2012-12/2019	Standard key 315MHz	B17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Sentra	09/2012-12/2016	Smart key 315MHz	B17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Sentra	09/2006-05/2016	315MHz	B16	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Skyline	01/2014-12/2018	315MHz		●	●	○	0	315Mhz	Continental	●	●
Nissan	Titan	01/2009-12/2015	315MHz A60	A60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Titan	10/2003-12/2007	315MHz	A60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Titan	01/2008-12/2008	Steel 315MHz	A60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Titan	01/2018-12/2019	433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	Titan	01/2016-12/2017	315MHz	A61	●	●	○	0	315MHz	Pacific	●	●
Nissan	Titan	11/2015-12/2017	433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	Titan	09/2013-12/2015	315MHz		●	●	○	0	315Mhz	Continental	●	●
Nissan	Titan	01/2008-12/2008	Alloy 315MHz	A60	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Titan Pro 4X	12/2013-08/2015	315MHz	B17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Titan XD	01/2016-12/2017	433 MHz	A61	●	●	○	0	433Mhz	Pacific	●	●
Nissan	Titan XD	01/2018-06/2020	433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	Versa	01/2013-06/2020	Standard key 315MHz	N17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Versa	05/2006-12/2008	Alloy 315MHz	SC11	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Versa	05/2006-12/2008	Steel 315MHz	SC11	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Versa	01/2009-12/2012	315MHz	SC11	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Versa	01/2012-06/2020	Smart key 315MHz	N17	●	●	○	0	315Mhz	Continental	●	●
Nissan	Versa	09/2014-07/2015	433MHz	N17	●	●	○	0	433Mhz	Schrader	●	●
Nissan	Versa Hatchback	01/2007-12/2010	315MHz	SC11	●	●	○	0	315Mhz	Continental	●	●
Nissan	Versa Sedan	01/2020-12/2020	433MHz		●	●	○	0	433Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Nissan	Xterra	01/2003-12/2004	315MHz	WD22	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Xterra	01/2005-12/2011	315MHz	N50	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Xterra	01/2012-06/2018	315MHz Schrader	N50	●	●	○	0	315Mhz	Schrader	●	●
Nissan	Xterra	01/2012-12/2015	433MHz		●	●	○	0	433MHz	Schrader	●	●
Nissan	Xterra	01/2012-12/2015	315MHz	N50	●	●	○	0	315Mhz	Continental	●	●
Oldsmobile	Alero	01/1999-12/2000	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Oldsmobile	Aurora	01/2001-12/2003	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Pontiac	Aztek	01/2003-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Pontiac	Bonneville	01/2000-12/2005	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Pontiac	G3	01/2009-12/2010	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Pontiac	G5	01/2009-12/2010	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	G5	01/2007-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	G6	01/2009-12/2010	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	G6	01/2008-12/2008	Clamp in 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Pontiac	G6	01/2008-12/2008	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	G8	01/2009-12/2009	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	G8	01/2008-12/2008	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	Grand Am	01/1999-12/2002	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Pontiac	Grand Prix	01/2004-12/2006	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Pontiac	Grand Prix	01/2006-12/2008	Clamp in 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Pontiac	Grand Prix	08/2007-12/2008	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	Montana	01/2008-12/2009	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	SV-6	01/2008-12/2009	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Pontiac	Solstice	01/2010-12/2010	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Pontiac	Solstice	01/2009-12/2009	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Pontiac	Solstice	12/2007-12/2008	315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Pontiac	Torrent	01/2008-12/2008	Snap in 315MHz		○	●	○	S	315Mhz	Schrader	●	●
Pontiac	Torrent	01/2009-12/2009	Clamp in 315MHz		●	●	●	0/S	315Mhz	Continental	●	●
Pontiac	Torrent	01/2007-12/2008	Clamp in 315MHz		○	●	○	S	315Mhz	Continental	●	●
Pontiac	Torrent	01/2009-12/2009	Snap in 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Pontiac	Vibe	01/2005-12/2007	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Pontiac	Vibe	01/2008-12/2010	315MHz		●	●	○	0/S	315Mhz	Pacific	●	●
Pontiac	Wave	01/2007-12/2009	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Porsche	718(982)	01/2017-06/2020	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911	01/2013-12/2016	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	911	02/2012-12/2016	433MHz	991	●	●	○	A	433Mhz	Huf/Beru	●	●
Porsche	911	07/2004-01/2012	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911	01/2017-12/2019	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Porsche	911	01/2005-12/2012	315MHz	997	●	●	○	0/A	315Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Porsche	911(991)	12/2011-12/2019	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	911(997)	01/2005-12/2008	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	911(997)	02/2005-03/2008	433MHz	997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911(997)	09/2015-12/2019	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911(997)	04/2008-08/2015	433MHz	997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911(997)	01/2009-12/2011	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	911(Turbo)	01/2007-12/2009	433MHz	997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911(Turbo)	01/2010-12/2019	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	911(Turbo)	01/2010-12/2012	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	911(Turbo)	01/2007-12/2009	315MHz	997	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	918 Spyder	01/2013-12/2015	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	01/2013-12/2016	315MHz	2. 7L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Boxster	01/2012-12/2016	433MHz	981	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	01/2009-12/2012	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Boxster	01/2009-12/2011	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	02/2005-12/2008	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	03/2016-12/2019	433Mhz 982	982	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	01/2004-12/2008	315MHz	987	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Boxster	01/2017-12/2019	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Carrera GT	09/2003-12/2011	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	11/2014-08/2017	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	09/2017-12/2019	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	01/2018-12/2018	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Cayenne	01/2013-10/2014	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	01/2011-12/2012	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	09/2010-12/2016	315MHz	92A	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayenne	01/2007-12/2010	433MHz	9PA1	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	01/2007-12/2010	315MHz	9PA1	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayenne	01/2002-12/2006	433MHz	9PA	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne	01/2002-12/2006	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayenne S	01/2008-12/2009	315MHz	4. 8L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayenne S	01/2007-12/2009	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne S	01/2010-05/2014	433MHz	4. 8L	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne S	09/2017-12/2019	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne S	01/2010-12/2012	315MHz	4. 8L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayenne S	06/2014-08/2017	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2013-12/2016	315MHz	2. 7L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2012-12/2016	433MHz	981	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2009-12/2012	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2009-12/2011	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2017-12/2019	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2005-12/2008	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
Porsche	Cayman	01/2005-12/2008	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	Cayman(718)	10/2016-06/2020	982 433MHz	982	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Porsche	GT3	01/2017-12/2019	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Porsche	GT3	01/2015-12/2015	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Porsche	GT3	01/2010-12/2016	433MHz	996/997	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	GT3	01/2007-12/2009	315MHz		●	●	○	O/A	315Mhz	Huf/Beru	●	●
Porsche	GT3	03/2006-12/2009	433Mhz	996	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Macan	01/2014-12/2015	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
Porsche	Macan	01/2018-12/2018	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
Porsche	Macan	01/2014-12/2019	433MHz	P0416	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Panamera	01/2010-12/2012	315MHz		●	●	○	O/A	315Mhz	Huf/Beru	●	●
Porsche	Panamera	01/2009-06/2013	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Panamera	01/2014-12/2016	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
Porsche	Panamera	07/2013-08/2017	433MHz	970	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Panamera	09/2017-06/2020	433MHz	970	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Panamera S	06/2009-12/2013	315MHz	4. 8L	●	●	○	O/A	315Mhz	Huf/Beru	●	●
Porsche	Panamera S	01/2009-06/2013	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Renault Samsung	QM3	01/2013-12/2015	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Renault Samsung	QM5	01/2014-12/2016	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	QM6	01/2016-12/2016	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM3	01/2013-12/2015	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM5	01/2010-12/2018	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM6	01/2015-12/2018	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM7	01/2012-12/2015	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Retrofit	ORO W401	01/2018-06/2019	433Mhz		○	●	○	S	433Mhz	ORO	●	●
Retrofit	ORO W410-A	01/2018-06/2019	433Mhz		○	●	○	A	433Mhz	ORO	●	●
Retrofit	ORO W410/W403	01/2018-06/2019	433Mhz		○	●	○	S	433Mhz	ORO	●	●
Retrofit	ORO W417-A	01/2019-12/2019	433Mhz		○	●	○	A/S	433Mhz	ORO	●	●
Retrofit	ORO W418-A	01/2018-06/2019	433Mhz		○	●	○	A/S	433Mhz	ORO	●	●
Rolls Royce	Black Badge	01/2019-06/2020	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Rolls Royce	Cullinan	03/2018-06/2020	433MHz	R31	○	●	○	A	433Mhz	Schrader	●	●
Rolls Royce	Dawn	01/2016-06/2020	433Mhz	RR6	○	●	○	C	433Mhz	Huf/Beru	●	●
Rolls Royce	Dawn	04/2014-12/2015	433MHz	RR6	○	●	○	C	433Mhz	Huf/Beru	●	●
Rolls Royce	Drophead Coupe	01/2008-12/2017	433Mhz	RR02	○	●	○	A	433Mhz	Huf/Beru	●	●
Rolls Royce	Ghost	05/2014-12/2017	433Mhz		○	●	○	C	433Mhz	Huf/Beru	●	●
Rolls Royce	Ghost	01/2009-12/2010	433Mhz	RR04	○	●	○	C	433Mhz	Huf/Beru	●	●
Rolls Royce	Ghost	01/2011-05/2014	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Rolls Royce	Phantom	01/2017-12/2019	PR11 433MHz		○	●	○	A	433Mhz	Schrader	●	●
Rolls Royce	Phantom	01/2012-12/2016	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Rolls Royce	Phantom	02/2003-12/2011	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Rolls Royce	Wraith	01/2012-04/2014	433Mhz	RR04	○	●	○	C	433Mhz	Huf/Beru	●	●
Rolls Royce	Wraith	05/2014-12/2017	433Mhz		○	●	○	C	433Mhz	Huf/Beru	●	●
Saab	9-3	01/2003-12/2007	433MHz		○	●	○	A	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Saab	9-3	01/2008-12/2012	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Saab	9-4X	01/2011-12/2012	315MHz		●	●	●	O	315Mhz	Schrader	●	●
Saab	9-5	01/2003-12/2007	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Saab	9-5	01/2008-12/2012	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Saab	9-5	01/2010-12/2012	315MHz		●	●	●	O/A	315Mhz	Schrader	●	●
Saab	9-7X	01/2005-12/2007	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Saab	9-7X	01/2008-12/2009	315MHz		●	●	●	S	315Mhz	Schrader	●	●
Saturn	Astra	01/2007-12/2008	Clamp in 315MHz		○	●	○	C	315Mhz	Schrader	●	●
Saturn	Astra	01/2008-12/2009	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Saturn	Astra	01/2010-12/2010	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Saturn	Astra	01/2010-12/2010	433MHz		○	●	○	C	433Mhz	Schrader	●	●
Saturn	Astra	01/2008-12/2009	Snap in 315MHz		○	●	○	C	315Mhz	Schrader	●	●
Saturn	Aura	01/2009-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Saturn	Aura	01/2008-12/2008	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Saturn	Aura	01/2007-12/2008	Clamp in 315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Saturn	Lambda	01/2007-12/2008	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Saturn	Outlook	01/2009-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Saturn	Outlook	01/2007-12/2008	315MHz		○	●	○	S	315Mhz	Continental	●	●
Saturn	Sky	01/2008-12/2008	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Saturn	Sky	01/2010-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Saturn	Sky	01/2009-12/2009	315MHz		●	●	●	O/S	315Mhz	Continental	●	●
Saturn	Vue	01/2007-12/2007	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Saturn	Vue	01/2008-10/2008	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Saturn	Vue	11/2008-12/2010	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
Scion	Corolla iM	01/2015-12/2016	315Mhz		●	●	○	O	315Mhz	Pacific	●	●
Scion	FR-S	01/2013-12/2016	315MHz		●	●	○	O	315Mhz	Pacific	●	●
Scion	IQ	01/2012-12/2015	315MHz		●	●	○	O	315Mhz	Pacific	●	●
Scion	TC	01/2006-12/2016	315MHz		●	●	○	O	315Mhz	Pacific	●	●
Scion	Tc	01/2005-05/2006	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Scion	XB	01/2007-12/2016	315MHz		●	●	○	O	315MHz	Pacific	●	●
Scion	XD	01/2008-12/2016	315MHz		●	●	○	O	315MHz	Pacific	●	●
Scion	iA	01/2015-06/2017	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Scion	iM	01/2015-05/2018	315Mhz		●	●	○	O	315Mhz	Pacific	●	●
Smart	42 EV	01/2013-12/2016	433Mhz		●	●	○	O	433Mhz	Schrader	●	●
Smart	Forfour	01/2005-06/2020	433Mhz	A453	●	●	○	O/A	433Mhz	Schrader	●	●
Smart	Fortwo	01/2008-12/2015	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Smart	Fortwo	01/2016-12/2019	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Subaru	Ascent	01/2018-12/2020	433Mhz	HR3	●	●	○	O	433Mhz	Schrader	●	●
Subaru	B9 Tribeca	01/2006-12/2008	315MHz		●	●	○	O	315Mhz	Schrader	●	●
Subaru	BRZ	01/2013-12/2019	315MHz		●	●	○	O	315Mhz	Pacific	●	●
Subaru	Crosstrek	01/2018-12/2019	433Mhz	HR3	●	●	○	O	433Mhz	Schrader	●	●
Subaru	Crosstrek	01/2016-12/2017	315Mhz		●	●	○	O	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Subaru	Forester	01/2018-12/2020	433MHz	FM5/PF3	●	●	○	0	433Mhz	Schrader	●	●
Subaru	Forester	01/2016-12/2019	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Forester	01/2008-12/2015	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Impreza	01/2017-06/2020	433Mhz	HR3	●	●	○	0	433Mhz	Schrader	●	●
Subaru	Impreza	01/2016-12/2017	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Impreza	01/2008-12/2015	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Impreza	01/2007-12/2007	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Legacy	01/2018-12/2019	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Subaru	Legacy	01/2016-12/2017	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Legacy	01/2008-12/2015	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Legacy	01/2004-12/2007	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Outback	01/2018-12/2020	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Subaru	Outback	07/2015-12/2017	315Mhz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Outback	01/2008-06/2015	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Outback	01/2004-12/2007	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	Tribeca	01/2008-12/2014	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	WRX	01/2019-06/2020	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Subaru	WRX	06/2014-12/2018	315Mhz		●	●	○	0	315Mhz	Schrader	●	●
Subaru	XV Crosstrek	01/2018-12/2019	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Subaru	XV Crosstrek	01/2013-12/2019	315MHz		●	●	○	0	315Mhz	Schrader	●	●
Suzuki	Equator	01/2009-12/2013	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Suzuki	Forenza	01/2007-12/2008	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Suzuki	Grand Vitara	01/2005-12/2014	315MHz		○	●	○	C	315MHz	Schrader	●	●
Suzuki	Kizashi	01/2010-12/2013	315MHz		○	●	○	C	315Mhz	Continental	●	●
Suzuki	Reno	01/2007-12/2008	315MHz		●	●	○	0/S	315Mhz	Schrader	●	●
Suzuki	SX4	01/2007-12/2014	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
Suzuki	Super Carry	01/2019-12/2019	433Mhz		○	●	○	C	433Mhz	Orange	●	●
Suzuki	Verona	01/2005-12/2006	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Suzuki	XL-7	01/2005-06/2006	315MHz		○	●	○	C	315Mhz	Schrader	●	●
Suzuki	XL-7	07/2006-12/2011	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
Tesla	Model 3	01/2016-06/2020	433Mhz		○	●	○	A	433Mhz	Continental	●	●
Tesla	Model S	01/2012-09/2014	433MHz		○	●	○	A	433Mhz	Baolong	●	●
Tesla	Model S	10/2014-06/2020	433MHz		○	●	○	A	433Mhz	Continental	●	●
Tesla	Model X	01/2016-06/2020	433MHz		○	●	○	A	433Mhz	Continental	●	●
Tesla	Roadster	01/2008-12/2010	Huf 433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Tesla	Roadster	01/2010-12/2012	Baolong 433MHz		○	●	○	A	433Mhz	Baolong	●	●
Toyota	4 Runner	01/2020-12/2020	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	4 Runner	09/2006-08/2017	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	4 Runner	09/2017-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	4 Runner	01/2003-08/2006	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	86	01/2017-12/2019	315Mhz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	AVANZA	09/2016-12/2019	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Toyota	Alphard	01/2015-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Avalon	08/2006-10/2012	Japan/USA 315MHz		●	●	○	0	315Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Toyota	Avalon	10/2015-12/2019	315MHz PAXPMVC015		●	●	○	0/A	315Mhz	Pacific	●	●
Toyota	Avalon	11/2012-12/2019	315MHz PAXPMVC010		●	●	○	0	315Mhz	Pacific	●	●
Toyota	C-HR	01/2016-12/2019	433MHz	560A	●	●	○	0/A	433Mhz	Pacific	●	●
Toyota	C-HR	01/2017-12/2019	315MHz		●	●	○	0/A	315Mhz	Pacific	●	●
Toyota	C-HR	01/2020-12/2020	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Camry	10/2011-12/2019	C010 315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Camry	01/2004-12/2005	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Toyota	Camry	01/2006-09/2011	Japan/USA 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Camry	09/2014-12/2019	C015 315MHz		●	●	○	0/A	315MHz	Pacific	●	●
Toyota	Camry Hybrid	09/2014-12/2017	315MHz		●	●	○	0/A	315MHz	Pacific	●	●
Toyota	Corolla	08/2013-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Corolla	01/2006-08/2013	Japan/USA 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Corolla	01/2005-06/2007	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Toyota	Corolla	02/2019-06/2020	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Corolla Hatchback	01/2019-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Corolla iM	06/2015-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	FJ Cruiser	06/2014-12/2019	433MHz	155L	●	●	○	0	433Mhz	Pacific	●	●
Toyota	FJ Cruiser	01/2007-12/2014	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	FR-S	01/2017-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	GT86	01/2017-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Hiace	10/2014-12/2019	433MHz		●	●	○	0	433MHz	Pacific	●	●
Toyota	Highlander	01/2014-12/2017	Smart Key 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Highlander	01/2007-12/2013	Japan/USA 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Highlander	01/2018-12/2019	Smart Key 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Highlander	01/2014-12/2019	Standard Key 315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Hilux	06/2014-12/2019	433Mhz	669L/640A	●	●	○	0	433Mhz	Pacific	●	●
Toyota	INNOVA	09/2016-12/2019	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Toyota	Land Cruiser	10/2015-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser	01/2006-09/2015	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Land Cruiser	01/2005-12/2005	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Land Cruiser	01/2020-12/2020	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser Prado	10/2017-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser Prado	01/2014-09/2017	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Matrix	01/2007-12/2014	Japan/USA 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Mirai	01/2016-12/2020	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Prius	01/2019-12/2020	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Prius	01/2016-12/2018	315MHz		●	●	○	0	315Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Toyota	Prius	01/2013-12/2015	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Prius	01/2006-12/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Prius C	01/2012-12/2020	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Prius Prime	01/2016-12/2018	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Prius V	01/2017-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Prius V	01/2012-12/2016	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	RAV4	11/2005-12/2012	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	RAV4	01/2019-12/2020	Pacific 315MHZ		●	●	○	0	315MHz	Pacific	●	●
Toyota	RAV4	12/2018-12/2019	TRW 315Mhz		●	●	○	0	315Mhz	TRW	●	●
Toyota	RAV4	01/2013-12/2018	TRW 315MHZ		●	●	○	0	315Mhz	TRW	●	●
Toyota	RAV4	01/2013-12/2018	Pacific 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	RUSH	01/2018-12/2019	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Toyota	Sequoia	01/2020-12/2021	315MHZ		●	●	○	0	315MHZ	Pacific	●	●
Toyota	Sequoia	01/2009-07/2017	315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Sequoia	01/2008-12/2008	Alloy/Steel 315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Sequoia	01/2004-12/2007	Alloy/Steel 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Sequoia	08/2017-12/2019	315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Sienna	01/2013-02/2016	433MHz		●	●	○	0	433MHZ	TRW	●	●
Toyota	Sienna	01/2006-12/2020	315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Sienta	11/2016-12/2019	315MHZ		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Solara	01/2006-12/2011	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Tacoma	01/2005-12/2009	Alloy 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Tacoma	01/2005-12/2009	Steel 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Tacoma	09/2015-12/2020	315MHz		●	●	○	0	315MHZ	Pacific	●	●
Toyota	Tacoma	01/2010-08/2015	Steel 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Tacoma	01/2010-08/2015	Alloy 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Tundra	01/2020-12/2020	Steel 315MHZ		●	●	○	0	315MHZ	Pacific	●	●
Toyota	Tundra	01/2020-12/2020	Alloy 315MHZ		●	●	○	0	315MHZ	Pacific	●	●
Toyota	Tundra	08/2017-12/2019	Alloy 315Mhz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Tundra	08/2017-12/2019	Steel 315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Tundra	01/2012-07/2017	315Mhz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Tundra	01/2007-12/2011	Steel 315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Tundra	01/2007-12/2011	Alloy 315MHz		●	●	○	0	315Mhz	TRW	●	●
Toyota	Tundra	01/2005-12/2006	Steel 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Tundra	01/2005-12/2006	Alloy 315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Venza	01/2009-12/2016	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Vios	01/2012-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Yaris	01/2012-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Yaris	01/2007-12/2011	315MHz		●	●	○	0	315Mhz	Pacific	●	●
Toyota	Yaris iA	01/2017-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Toyota	iA	01/2017-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Toyota	iM	01/2017-12/2019	315MHz		●	●	○	0	315Mhz	Pacific	●	●



Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
VPG	MV-1	01/2011-12/2016	315MHz		○	●	○	S	315Mhz	Schrader	●	●
Volkswagen	Amarok	01/2014-06/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Arteon	06/2017-06/2020	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Volkswagen	Atlas	01/2017-12/2019	433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Atlas	01/2017-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Beetle	01/2012-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Beetle	01/2007-12/2011	315MHz		●	●	○	A	315Mhz	Continental	●	●
Volkswagen	CC	01/2009-12/2011	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	CC	06/2011-12/2018	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	CC	01/2018-12/2019	MQB 433Mhz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	EOS	01/2007-12/2017	315MHz		●	●	○	A	315Mhz	Continental	●	●
Volkswagen	GLI	01/2008-12/2011	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	GTI	01/2006-12/2012	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	GTI	01/2012-12/2019	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Golf	01/2010-12/2011	315MHz		●	●	○	A	315Mhz	Continental	●	●
Volkswagen	Golf	01/2009-12/2019	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Golf	01/2006-12/2007	315MHz		●	●	○	A	315Mhz	Continental	●	●
Volkswagen	Golf	01/2013-06/2020	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Golf	01/2012-12/2012	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Jetta	01/2013-12/2019	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Jetta	01/2013-12/2019	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
Volkswagen	Jetta	01/2011-12/2012	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Jetta	01/2006-12/2012	315MHz		●	●	○	A	315Mhz	Continental	●	●
Volkswagen	New Beetle	01/2012-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	New Beetle	01/2007-12/2011	315MHz		●	●	○	A	315Mhz	Continental	●	●
Volkswagen	Passat	01/2006-12/2011	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	Passat	01/2012-12/2019	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Passat	01/2011-12/2011	433MHz		●	●	○	O	433Mhz	Huf/Beru	●	●
Volkswagen	Phaeton	06/2007-12/2010	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Phaeton	01/2011-12/2012	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Phaeton	01/2003-05/2007	315MHz		●	●	○	O/A	315Mhz	Huf/Beru	●	●
Volkswagen	Phaeton	01/2003-05/2007	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Phaeton	06/2007-12/2010	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	R32	01/2008-12/2011	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	R36	01/2009-12/2011	433MHz		●	●	○	A	433Mhz	Continental	●	●
Volkswagen	Rabbit	01/2006-12/2010	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	Routan	01/2011-12/2015	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Volkswagen	Routan	01/2009-12/2010	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volkswagen	Routan	01/2005-12/2008	433MHz		●	●	○	O	433Mhz	Continental	●	●
Volkswagen	T-Cross	07/2019-06/2020	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Tiguan	01/2012-12/2019	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Tiguan	01/2011-12/2019	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Tiguan	01/2009-12/2011	315MHz		●	●	○	O/A	315Mhz	Continental	●	●
Volkswagen	Tiguan L	01/2018-12/2019	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Touareg	08/2014-06/2020	433Mhz	7P5/7P6108	●	●	○	O/A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Volkswagen	Touareg	01/2012-07/2014	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Touareg	01/2007-12/2016	315MHz		●	●	○	O/A	315Mhz	Huf/Beru	●	●
Volkswagen	Touareg	01/2007-12/2011	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volkswagen	Touareg	01/2002-12/2006	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Volvo	C30	01/2011-12/2013	433Mhz	Y279	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	C30	01/2006-12/2010	433Mhz	Y279	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	C70	01/2011-06/2014	433Mhz	V70064	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	C70	01/2008-12/2010	433Mhz	V70064	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	C70	01/2006-12/2007	433Mhz	V70064	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S40	01/2003-12/2010	433Mhz	V40044	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S40	01/2011-06/2014	433Mhz	V40044	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S60	01/2011-12/2014	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S60	01/2015-12/2019	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S60	02/2013-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S60	01/2004-12/2010	315MHz		●	●	○	A	315Mhz	Schrader	●	●
Volvo	S60	07/2000-02/2010	433Mhz	P24/V664	●	●	○	A	433Mhz	Schrader	●	●
Volvo	S80	07/2014-01/2017	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S80	03/2013-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S80	01/2010-06/2014	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S80	01/2004-12/2009	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	S80	01/2004-12/2007	315MHz		●	●	○	A	315Mhz	Schrader	●	●
Volvo	S90	01/2016-06/2020	433Mhz	V541	●	●	○	O/A	433Mhz	Schrader	●	●
Volvo	S90	01/2016-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V40	01/2012-06/2020	433Mhz	Y555, Y556	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	V50	01/2011-12/2012	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	V50	01/2005-12/2010	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	V60	11/2017-06/2020	433Mhz		●	●	○	O/A	433Mhz	Schrader	●	●
Volvo	V60	09/2015-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V60	07/2014-12/2019	433Mhz 31341893		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	V60 Cross Country Wagon	01/2015-12/2018	433Mhz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	V70	01/2008-12/2014	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	V70	01/2000-12/2007	315MHz		●	●	○	A	315Mhz	Schrader	●	●
Volvo	V70	01/2000-12/2007	433Mhz	Y285/V764	●	●	○	A	433Mhz	Schrader	●	●
Volvo	V90	01/2017-12/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V90	01/2015-06/2020	433Mhz	V542	●	●	○	O/A	433Mhz	Schrader	●	●
Volvo	XC40	01/2017-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC60	01/2015-06/2020	433Mhz	Y413	●	●	○	O/A	433Mhz	Continental	●	●
Volvo	XC60	01/2015-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC60	01/2009-12/2014	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	XC60	01/2009-12/2010	315MHz		●	●	○	O/A	315Mhz	Schrader	●	●
Volvo	XC70	01/2015-12/2017	433Mhz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	XC70	01/2008-12/2009	433MHz		●	●	○	O/A	433Mhz	Continental	●	●
Volvo	XC70	01/2003-12/2007	315MHz		●	●	○	A	315Mhz	Schrader	●	●
Volvo	XC70	01/2003-12/2007	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Volvo	XC70	01/2010-12/2014	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Volvo	XC90	09/2016-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC90	01/2015-12/2019	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
Volvo	XC90	01/2008-12/2008	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Volvo	XC90	01/2004-12/2014	315MHz		●	●	○	0/A	315Mhz	Schrader	●	●
Volvo	XC90	01/2003-12/2007	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●