

Last Modified: 5-3-2010	6.4 T	From: 200904
Model Year: 2010	Model: Prius	Doc ID: RM000003RRZ007X
Title: 2ZR-FXE COOLING: EXHAUST HEAT RECIRCULATION SYSTEM: PROBLEM SYMPTOMS TABLE (2010 Prius)		

PROBLEM SYMPTOMS TABLE

HINT:

- Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.
- Inspect the fuses and relays related to this system before inspecting the suspected areas below.

Exhaust Heat Recirculation System

SYMPTOM	SUSPECTED AREA	SEE PAGE
Engine overheating	Engine coolant leaks (for engine side)	INFO
	Engine coolant leaks (for exhaust heat recirculation system)	INFO
	Front exhaust pipe assembly	INFO
	Exhaust pipe gas control actuator	INFO
	Exhaust heat recirculation system circuit	INFO
	Engine coolant temperature sensor (for exhaust heat recirculation system)	INFO

