



Report Number: TOPDON1779838420

SN: 110453W5D8055H

Date Created: 2026-05-26

TOPDON ID: 911HZYCFEO

TOYOTA-PRIUS-After 2003/09_Fault Code Report

Plate Number:

Make:TOYOTA

Model:PRIUS

Year:After 2003/09

Distance Traveled:

Engine:1NZ-FXE

Sub Model:

Diagnostic Time:2026-05-26 19:33:40

Vehicle Software Version:V5.50

Diagnostic Application Version:V6.35.300

VIN:JTDKB20U363145297

Diagnostic Scan Path:Automatic/Japan/Prius/
NHW/1NZ-FXE/After 2003/09/ABS/VSC/
TRC(TRAC)

Customer:

Phone Number of Customer:

Ticket No.:

Fault Code Report (2)

ABS/VSC/TRC(TRAC)

| DTC | Description | Status |
|-------|--|---------|
| C1241 | Low Battery Positive Voltage or Abnormally High Battery Positive Voltage | Current |
| C1256 | ACCumulator Low Pressure | Current |

Disclaimer

This diagnostic report is provided for the purpose of displaying diagnostic data and is for reference only. It does not constitute any judgment, conclusion, or basis for action. The Company shall not be liable for any decisions or actions taken by the user based on the content of this report.

When a user chooses to save the diagnostic report to the App client, the relevant report content will be stored in accordance with the App's functional requirements for the purpose of subsequent access.